| CERTIFICATE OF LOCATION | OF GOVERNMENT CORNER |
|---|---|
| EAST QUARTER Corner of Section 8 STATE OF MINNESOTA, County of NOBLES At the corner location shown on the sketch: On 11/12/02 found a 5/8" REROD DATE | , Township <u>102 N</u> , Range <u>43 W</u> , 5th P.M. |
| ☑ left monument as found, ☐ lo ☐ Onplaced a | owered monument, 🗆 removed monument (explain) |
| SKETCH OF F | REFERENCE TIES |
| - N - | NORTHEAST CORNER SECTION 8-102-43 5/8" REROD |
| NE 1/4 SEC 8-102-43 EAST 1/4 CORNER SECTION 8-102-43 5/8" REROD | NW 1/4 SEC 9-102-43 |
| SE 1/4 SEC 8-102-43 NAD83 (1996 ADJUSTMENT) STATE PLANE COORDINATES NOBLES COUNTY DATUM | SW 1/4 SEC 9-102-43 SOUTHEAST CORNER SECTION 8-102-43 1/2" REROD |
| N= 155653.025 E= 483293.093 | BOOK: NOBLES CO. PG. 18 1:\NOBLS\CERTIFICATES\E8-102-43 |
| Statement of evidence relative to this corner location is on back of page. | |
| I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision. 10/4/05 | OFFICE OF THE COUNTY RECORDER County of I hereby certify that this document was filed in the Co. Recorders office atM. on the |
| JANELE FOWLDS DATE | day of A.D., 19 |
| Registration No. <u>26748</u> ☑ Land surveyor, □ Professional Engineer | County Recorder, Deputy |
| ☐ County Surveyor, ☐ County Engineer | DOCUMENT NO. |

Statement of Evidence

East Quarter Corner Section 8, Township 102 North, Range 43 West

According to the Original Survey notes located in the Secretary of States Office, the East Quarter of Section 8 was established as follows: North between Sections 8 & 9, Variance 11 degrees 15 minutes, at 40.00 chains set a post in mound with pits for the Quarter Section Corner.

| 1965 | Nobles County Highway Department records show the East Quarter was reestablished and that an iron pin was placed. No mention how the corner was reestablished. |
|------|--|
| 1966 | Nobles County Highway Department records show an iron pin. |
| 1974 | Nobles County Highway Department records show an iron pin. |
| 1994 | Nobles County Highway Department records show a 1 ¾" PK Nail was placed after overlay, with ties as follows: 2X2 Hub in slope – Northeast 28.12' 60-penny common spike in slope – Northwest 38.16' 2X2 Hub inslope – Southeast 30.72' 60-penny common spike in slope – Southwest 31.60' |
| 2002 | On November 12, Bolton & Menk, Inc. found a PK Nail at the surface of a bituminous road, and a 5/8" Rerod 0.2' below the surface of the road. |