514 34 104 42



Index ____A-15

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER	
NORTH QUARTER Corner of Secti	on _3, Township103N, Range42W
5th Principal Meridian, State of Minnesota, County of Nobles.	
At the corner location shown on the sketch:	
On found a	
90 mg/s	d monument
X On 12/28/17 placed a ½" REBAR CAPPLE DATE	ED 49563 FROM HIGHWAY PLANS
SKETCH OF REFERENCE TIES	
NGS MARKER	SW CORNER ELECTRIC BOX
\ \ \	ok, /
61/2 81/0 81/0	1005,70
	(PI) CSAH 16
N02°E 18.00	/ COAN TO
REBAR CAPPED LS 49563	
(SECTION CORNER)	
	4
Statement of evidence for this corne	N.T.S.
	in location is on back of this page.
I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.	DOCUMENT NUMBER A 357384 Certified, Filed and or Recorded or February 28, 2018 12:05 PM
Signature 75/W.	Lyan Wilson
Date 1/8/18 License No. 49563	NOBLES COUNTY RECORDER LYNN M. WILSON 507-295-5268
Title:	Pages: 2
☐ County Surveyor ☐ County Engineer	

KRIS WROOLIE Minnesota License No. 49563

Statement of Evidence:

A-15

North Quarter Corner of Section 3, Township 103 North, Range 42 West, 5th Principal Meridian, Nobles County, Minnesota.

1869-Deputy Surveyor set a post in mound with pits.

1897- Nobles County Highway Department "Corner Ties Book" calls for a stone to mark the corner location.

1922- Nobles County Highway Department "Corner Ties Book" calls for a stone to mark the corner location.

1943- Nobles County Highway Department "Corner Ties Book" calls for a stake to mark the corner location.

1955- Nobles County Highway Department "Corner Ties Book" calls for a stone and a placed iron pin mark the corner location. Highway plans show the corner to be 18' south of the PI.

1967- Nobles County Highway Department "Corner Ties Book" calls for a placed iron rod to mark the corner location.

2016- Nobles County Highway Department "Corner Ties Book" calls for a PK nail was set after an overlay to mark the corner location.

2017- Westwood Professional Services recovered a PK nail at the highway PI. A ½" rebar capped 49563 was placed 18' south of the PI per highway plans for the corner. Ties were found or set as shown on the front of this certificate

Analysis of the recovered data, field evidence and survey measurements, indicates that the monument found is the correct perpetuation of this corner. For additional information concerning this corner please contact Westwood Professional Services.

sils in