Index No. _____

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

NORTH QUARTER Corner of Section 15, Township 102 N, Range 41 W, 5th P.M.

STATE OF MINNESOTA, County of NOBLES


At the corner location shown on the sketch:

☒ On 3/08/06 (DATE) found a IRON

☐ left monument as found, ☐ lowered monument, ☐ removed monument (explain)

☐ On _____ (DATE) placed a _____

SKETCH OF REFERENCE TIES



NAD83 (1996 ADJUSTMENT)
STATE PLANE COORDINATES
NOBLES COUNTY DATUM

N= 147922.258
E= 585118.252

BOOK:SEE FAIRMONT
I:\NOBLS\CERTIFICATES\2005\CAD\N15-102-41

Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

Janele Fowlds — 4-24-06

JANELE FOWLDS — DATE

Registration No. 26748

☒ Land surveyor, ☐ Professional Engineer

☐ County Surveyor, ☐ County Engineer

OFFICE OF THE COUNTY RECORDER

County of _____

I hereby certify that this document was filed in the Co. Recorders office at ___.M. on the _____ day of _____ A.D., 19___

County Recorder _____

By _____, Deputy

DOCUMENT NO. _____

Statement of Evidence

North Quarter Corner Section 15, Township 102 North, Range 41 West

Original Notes

1960 Nobles County Highway Department records show a stone monument with the following ties:

FE Post – West 9.37'
FE Post – North 9.92'
FE Post – South 19.18'

2003 On July 14, Bolton & Menk, Inc., Mankato, searched for evidence of a corner but found nothing.

2006 On March 28, Bolton & Menk, Inc., Fairmont, found a iron at the intersection of two fences. One fence running north and south through the iron and the other running west from the iron.

The evidence is not conclusive as to the true corner location, however the occupational and collateral evidence suggest that this is a reasonable location as to the corner. Additional information regarding the preparation of this certificate can be obtained by contacting: Bolton & Menk, Inc., Mankato, MN.