Index No. _____

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

NORTHEAST Corner of Section 12, Township 102 N, Range 44 W, 5th P.M.

STATE OF MINNESOTA, County of NOBLES


At the corner location shown on the sketch:

☒ On 11/08/02 (DATE) found a 5/8" REROD

☒ left monument as found, ☐ lowered monument, ☐ removed monument (explain)

☐ On _____ (DATE) placed a _____

SKETCH OF REFERENCE TIES



NAD83 (1996 ADJUSTMENT)
STATE PLANE COORDINATES
NOBLES COUNTY DATUM

N= 158227.982
E= 472664.690

BOOK: NOBLES CO. PG. 5
I:\NOBLS\CERTIFICATES\NE12-102-44

Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

Janele Fowlds — JANELE FOWLDS — 4-24-06 (DATE)

Registration No. 26748

☒ Land surveyor, ☐ Professional Engineer

☐ County Surveyor, ☐ County Engineer

OFFICE OF THE COUNTY RECORDER

County of _____

I hereby certify that this document was filed in the Co. Recorders office at ___.M. on the _____ day of _____ A.D., 19___

County Recorder _____

By _____, Deputy

DOCUMENT NO. _____

Statement of Evidence

Northeast Corner Section 12, Township 102 North, Range 44 West

According to the Original Survey notes located in the Secretary of States Office, the Northeast Corner of Section 12 was established as follows: North on the true line between Ranges 43 & 44, Township 102, between Sections 7 & 12, Variance 12 degrees, at 80.00 chains set a post in mound for the corner to Sections 6, 7, 1, & 12.

1936 Nobles County Highway Department records show a stone monument.

1939 Nobles County Highway Department records show a stone monument.

2002 On November 8, Bolton & Menk, Inc. found a 5/8" Rerod 0.2' below the surface at the intersection of township roads.

The evidence is not conclusive as to the true corner location, however the occupational and collateral evidence suggest that this is a reasonable location as to the corner. Additional information regarding the preparation of this certificate can be obtained by contacting: Bolton & Menk, Inc., Mankato, MN.