

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

NORTH QUARTER Corner of Section 28, Township 102 N, Range 40 W, 5th P.M.

STATE OF MINNESOTA, County of NOBLES


At the corner location shown on the sketch:

On 7/16/03 found a ALUMINUM CAP
DATE

left monument as found, lowered monument, removed monument (explain)

On _____ placed a _____
DATE

SKETCH OF REFERENCE TIES



NAD83 (1996 ADJUSTMENT)
STATE PLANE COORDINATES
NOBLES COUNTY DATUM

N= 142579.346
E= 581183.723

BOOK: 110 PG. 43
I:\NOBLES\CERTIFICATES\2005\CAD\N28-102-40

Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

Janele Fowlds 4-24-06
JANELE FOWLDS DATE

Registration No. 26748

Land surveyor, Professional Engineer
 County Surveyor, County Engineer

OFFICE OF THE COUNTY RECORDER

County of _____

I hereby certify that this document was filed in the Co. Recorders office at _____ M. on the _____ day of _____ A.D., 19__

County Recorder _____

By _____, Deputy

DOCUMENT NO. _____

Statement of Evidence

North Quarter Corner Section 28, Township 102 North, Range 40 West

Original Notes

- 1892 Nobles County Highway Department records show a stone monument being set.
- 1900 Nobles County Highway Department records show a stone monument.
- 1967 Nobles County Highway Department records show a wood stake.
- 1995 Nobles County Highway Department records show Madsen Land Surveying Inc., Fairmont, found a 3/4" iron pipe with the following ties:
Disc in Cor FE Post – North 33.25'
Top Bolt of Fire Hyd – Southeast 43.96'
1 1/2" Steel Post – Northeast 37.25'
- 1998 Field notes received by Madsen Land Surveying Inc., Fairmont, shows a 3/4" iron pipe was found, removed and replaced with a 5/8" iron rod and aluminum cap to surface. The ties are as follows:
Top Fire Hyd – Southeast 44.03'
Nail & Disk in Cor FE Post – North 33.32'
Steel Post – Northeast 37.27'
Fence to North – West 1.0'
- 2003 On July 16, Bolton & Menk, Inc., Mankato, found an aluminum cap at surface.