Index	No.	
HIDEY	110.	

CERTIFICATE OF LOCATION	OF GOVERNMENT CORNER		
EAST QUARTER Corner of Section 13 , Township 102 N , Range 44 W , 5th P.M.  STATE OF MINNESOTA, County of NOBLES  At the corner location shown on the sketch:  On 11/08/02 found a CAST IRON MONUMENT			
□ On placed a DATE	ered monument, $\square$ removed monument (explain)		
SKETCH OF REFERENCE TIES			
- <b>N</b> -	NE CORNER SECTION 13-102-44 GEAR SPIKE		
NE 1/4 SEC 13-102-44  EAST 1/4 CORNER  SECTION 13-102-44  CAST IRON MONUMENT	NW 1/4 SEC 18-102-43		
SE 1/4 SEC 13-102-44			
	SW 1/4 SEC 18-102-43		
NAD83 (1996 ADJUSTMENT) STATE PLANE COORDINATES NOBLES COUNTY DATUM			
N= 150339.279 E= 472609.273	BOOK: NOBLES CO. PG. 4 I:\NOBLS\CERTIFICATES\E13-102-44		
Statement of evidence relative to this corner location is on back of page.			
I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.  OFFICE OF THE COUNTY RECORDER  County of			
JANELE FOWLDS 4-24-06 DATE	I hereby certify that this document was filed in the Co. Recorders office atM. on the A.D., 19		
Registration No. <u>26748</u> ☑ Land surveyor, □ Professional Engineer	County Recorder		
☐ County Surveyor, ☐ County Engineer	By, Deputy DOCUMENT NO		

## Statement of Evidence

East Quarter Corner Section 13, Township 102 North, Range 44 West

According to the Original Survey notes located in the Secretary of States Office, the East Quarter of Section 13 was established as follows: North on the true line between Ranges 43 & 44, Township 102, between Sections 13 & 18, Variance 12 degrees, at 40.00 chains set a post in mound for the Quarter Section Corner.

1978 Nobles County Highway Department records show a spike.

On November 8, Bolton & Menk, Inc. found a Cast Iron Monument 0.5' below the surface at the intersection of a minimum maintenance road to the North and to the East.

The evidence is not conclusive as to the true corner location, however the occupational and collateral evidence suggest that this is a reasonable location as to the corner. Additional information regarding the preparation of this certificate can be obtained by contacting: Bolton & Menk, Inc., Mankato, MN.