	index No.
CERTIFICATE OF LOCATION	OF GOVERNMENT CORNER
NORTH QUARTER Corner of Section 16	, Township <u>102 N</u> , Range <u>43 W</u> , 5th P.M.
STATE OF MINNESOTA, County of NOBLES	
At the corner location shown on the sketch:	
☑ On 11/08/02 found a NOTHING	
☐ left monument as found. ☐ lo	wered monument, 🗆 removed monument (explain)
☑ On 6/16/05 placed a RAILROAD SPIK	
DATE	
SKETCH OF R	EFERENCE TIES
 	
1 - N -	The state of the s
'	
SW 1/4 SEC 9-102-43	
1 377 77 320 3702 770	SE 1/4 SEC 9-102-43
NODTH 4 (4 CORNER	32 7 7 32 3 102 - 10
NORTH 1/4 CORNER SECTION 16-102-43	
RAILROAD SPIKE	
2663.90'	2663.90'
NORTHWEST CORNER SECTION 16-102-43 1/2" REROD	NORTHEAST CORNER SECTION 16-102-43 BRASS PLUG
NW 1/4 SEC 16-102-43	·
7777 77 32 37 70 70 2 70	NE 1/4 SEC 16-102-43
NAD83 (1996 ADJUSTMENT)	
STATE PLANE COORDINATES NOBLES COUNTY DATUM	
N= 152969.732	
E= 485935.900	BOOK: NOBLES CO. PG. 1 I:\NOBLS\CERTIFICATES\N16-102-43
Statement of evidence relative to this corne	er location is on back of page.
I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.	OFFICE OF THE COUNTY RECORDER County of
Januatorillos 10/4/05 JANELE FOWLDS DATE	I hereby certify that this document was filed in the Co. Recorders office atM. on the day of A.D., 19
Registration No. <u>26748</u>	County Recorder
☑ Land surveyor, ☐ Professional Engineer	
│	DOCUMENT NO.

÷...

Statement of Evidence

North Quarter Corner Section 16, Township 102 North, Range 43 West

According to the Original Survey notes located in the Secretary of States Office, the North Quarter of Section 16 was established as follows: East on a random line between Sections 9 & 16, Variance 11 degrees 45 minutes, at 40.00 chains set temporary quarter post, at 80.52 chains intersect North South line 35 links South of the corner to Sections 9, 10, 15, & 16. South 89 degrees 45 minutes West, between Sections 9 & 16, Variance 11 degrees 45 minutes, at 40.26 chains set post in mound with pits for the Quarter Section Corner.

1959	Nobles County Highway Department records show an iron pin with ties as
	follows:

Fence Post - Northeast 45.09'

- On November 8, Bolton & Menk, Inc. searched for the corner and found nothing.
 Bolton & Menk, Inc. calculated a position half way and on line between the
 Northeast and the Northwest Corners of the Section.
- On June 16, Bolton & Menk, Inc. set a railroad spike, in the bituminous surface, at the previously calculated position.