



Index ____C-17

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER	
EAST QUARTER Corner of Se	ction _3_ , Township _103N , Range _41W
5th Principal Meridian, State of Minnesota, Count	
At the corner location shown on the sketch:	
X On	EAST OF CENTERLINE AND ON A FENCE LINE TO THE EAST
X left monument as found lowe	ered monument
On placed a	
-	
	SKETCH OF REFERENCE TIES
A V.E.	
SET 3" REBAR	
ر الراق الراق الراق ال	
5/30. 8/30.	
SET &" REBAR	SET §" REBAR
Statement of solders for the	N.T.S.
I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Lan Surveyor under the laws of the State of Minnesota.	DOCUMENT MIMBER A 357459 Certified, Filed and or Recorded on March 03, 2018 9:30 AM
Signature	Lyon William of
Date	- MOBLES COUNTY RECORDER LYNN M. WILSON
Title:	507-295-5258 Pages: 2
X Land Surveyor Professional Engineer	는 마음 등 기계
☐ County Surveyor ☐ County Engineer	

KRIS WROOLIE Minnesota License No. 49563

Statement of Evidence:

C-17

East Quarter Corner of Section 3, Township 103 North, Range 41 West, 5th Principal Meridian, Nobles County, Minnesota.

1868-Deputy Surveyor Jewett Howe set a post in mound with pits for the 1/4 section corner.

Date Unknown-In Survey Book A-1, page 24, 1/4 corner is shown to be 40.39 chains (2665.74 ft.) from the SW corner of section 2.

2017-On November 8th, Westwood Professional Services found a 5/8" rebar of unknown origin online with the fence to the east and 6 ft east of north/south centerline. Overall distance of the east line of section 3 fits GLO within 14.57 ft. The found 5/8" rebar is 21.65 ft short of the GLO single proportion distance and 40.15 ft. short of the distance shown in Survey Book A-1. The 5/8" rebar appears to have been set on line between the NW and SW corners of Section 2 and online with the fence line running east. The found 5/8" rebar is the best available evidence of the corner position. Accepting as the corner.

Analysis of the recovered data, field evidence and survey measurements, indicates that the monument found is the correct perpetuation of this corner. For additional information concerning this corner please contact Westwood Professional Services.

Trice.