19 6 10° 42



Index _____C-25

| CERTIFICATE OF LOCATION OF GOVERNMENT CORNER | |
|---|--|
| EAST QUARTER Corner of Section | n <u>1</u> , Township <u>103N</u> , Range <u>43W</u> |
| 5th Principal Meridian, State of Minnesota, County of Nobles. | |
| At the corner location shown on the sketch: | |
| X On 12/28/17 found a 5/8" REBAR AT THE CENTERLINE INTERSECTION | |
| ☐ left monument as found ☐ lowered monument ☐ removed monument (explain) | |
| Onplaced a | |
| | |
| SKETCH OF REFERENCE TIES | |
| GRAIN ST. STSON STSON NORTH FACE OF STREET SIGN POST NOS STATION 5308 K STSON NORTH FACE OF STREET SIGN POST | |
| N.T.S. Statement of evidence for this corner location is on back of this page. | |
| I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota. | DISCURSENT MUMBER & 357420 Certified Tiled and or Maccondition Narch OL 2018 H 20 AM |
| Signature +5 W.L. Date 1/8/18 License No. 49563 Title: | Lynn de lideration of |
| X Land Surveyor Professional Engineer | Payer 2 |
| ☐ County Surveyor ☐ County Engineer | |

KRIS WROOLIE Minnesota License No. 49563

Statement of Evidence:

C-25

East Quarter Corner of Section 1, Township 103 North, Range 43 West, 5th Principal Meridian, Nobles County, Minnesota.

1869-Deputy Surveyor set a post in mound with pits.

1892- Nobles County Highway Department "Corner Ties Book" calls for a stone set to mark the corner location.

1917- Nobles County Highway Department "Corner Ties Book" calls for a stone set to mark the corner location.

2002 - Zieske Land Surveying showed an iron monument in place

2008 - Ulteig Engineers found a PK nail at the centerline intersection, set ties, and filed a Certificate of Location doc. no. 318105

2017- Westwood Professional Services recovered 5/8" rebar at the centerline intersection and one tie from the 2008 Certificate. Ties were found or set as shown on the front of this certificate

Analysis of the recovered data, field evidence and survey measurements, indicates that the monument found is the correct perpetuation of this corner. For additional information concerning this corner please contact Westwood Professional Services.

31,81