GUNY

Index ____E-17

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER	
NORTHEAST Corner of Section _	10 Township 103N Pages 43W
5th Principal Meridian, State of Minnesota, County of Nobles.	
At the corner location shown on the sketch:	
X On 12/01/17 found a PK NAIL AT THE CENTERLINE INTERSECTION DATE	
On placed a	
SKETCH OF REFERENCE TIES CENTER OF CHAIN LINK FENCE CORNER POST X 170TH ST. SKETCH OF REFERENCE TIES FOUND NAIL AND BOTTLE CAP IN NW FACE PP (1990) FOUND NAIL AND BOTTLE CAP IN SW FACE PP (1990) N.T.S.	
Statement of evidence for this corner location is on back of this page.	
I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.	DDCUMERI NIMBER A 357423 Cartified, Filed and or Recorded on March 01, 2018 9:40 AM
Signature 45 VVI. Date 1/8/18 License No. 49563	Lynn Willson
	NOBLES COUNTY RECORDER (V) LYMM WILSON 507-295-5288
Title:	poznakonos Pagest Z
☐ County Surveyor ☐ County Engineer	

KRIS WROOLIE Minnesota License No. 49563

Statement of Evidence:

E-17

Northeast Corner of Section 10, Township 103 North, Range 43 West, 5th Principal Meridian, Nobles County, Minnesota.

- 1869-Deputy Surveyor set a post in mound with pits.
- 1897- Nobles County Highway Department "Corner Ties Book" calls for an iron pin to mark the corner location.
- 1910- Nobles County Highway Department "Corner Ties Book" calls for an iron pin to mark the corner location.
- 1941- Nobles County Highway Department "Corner Ties Book" calls for a placed stake to mark the corner location.
- 1965- Nobles County Highway Department "Corner Ties Book" calls for a placed iron pin to mark the corner location.
- 1990- Nobles County Highway Department "Corner Ties Book" shows ties for the corner
- 2003- Nobles County Highway Department "Corner Ties Book" calls for a found iron pin and a PK nail set after an overlay to mark the corner location.
- 2017- Westwood Professional Services recovered a PK nail with a magnetic indication under it at the centerline intersection. Ties were found or set as shown on the front of this certificate

Analysis of the recovered data, field evidence and survey measurements, indicates that the monument found is the correct perpetuation of this corner. For additional information concerning this corner please contact Westwood Professional Services.

91/8/11