

Index E-13

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER	
NORTHEAST Corner of Section	on <u>9</u> , Township <u>103N</u> , Range <u>43W</u>
4th Principal Meridian, State of Minnesota, County	of Nobles.
At the corner location shown on the sketch:	
X On 12/01/17 found a PK NAIL AT THE CENTERLINE INTERSECTION DATE	
X left monument as found	
Onplaced a	
SKETCH OF REFERENCE TIES	
BULICK AVE.	WEST LEG OF MIN MAINT SIGN  170TH ST.
	N.T.S.
Statement of evidence for this corner is hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.	DDCUMENT NUMBER A 357421 Certified, Filed and or Recorded or March 01, 2018 9:30 AM
Signature + No. 49563  Date 1/8/18 License No. 49563	NOSLES COUNTY RECORDER (S
Title:	507-295-5258
X Land Surveyor Professional Engineer	¤a <sub>gus;</sub> ∑
☐ County Surveyor ☐ County Engineer	

## KRIS WROOLIE Minnesota License No. 49563

## **Statement of Evidence:**

E-13

Northeast Corner of Section 9, Township 103 North, Range 43 West, 5<sup>th</sup> Principal Meridian, Nobles County, Minnesota.

- 1869-Deputy Surveyor set a post in mound with pits.
- 1923- Nobles County Highway Department "Corner Ties Book" calls for a stone and a placed wood stake to mark the corner location.
- 1941- Nobles County Highway Department "Corner Ties Book" calls for a stake to mark the corner location.
- 1965- Nobles County Highway Department "Corner Ties Book" calls for a placed iron pin to mark the corner location.
- 1966- Nobles County Highway Department "Corner Ties Book" calls for a placed iron pin after an overlay to mark the corner location.
- 1979- Nobles County Highway Department "Corner Ties Book" calls for an iron pin to mark the corner location.
- 1990- Nobles County Highway Department "Corner Ties Book" shows ties for the corner
- 2003- Nobles County Highway Department "Corner Ties Book" calls for a found iron pin and a PK nail set after an overlay to mark the corner location.
- 2017- Westwood Professional Services recovered a PK nail with a magnetic indication under it at the centerline intersection. Ties were found or set as shown on the front of this certificate

Analysis of the recovered data, field evidence and survey measurements, indicates that the monument found is the correct perpetuation of this corner. For additional information concerning this corner please contact Westwood Professional Services.

8/8,1