	5 .7 7 (.		27	1
ndex	R-	15	100	日

CERTIFICATE OF LOCATION	OF GOVERNMENT CORNER			
NORTH QUARTER Corner of Section	on <u>27</u> , Township <u>104N</u> , Range <u>41W</u>			
5th Principal Meridian, State of Minnesota, County	W V-2			
At the corner location shown on the sketch:				
X On <u>11/09/2017</u> found <u>NOTHING.</u>	On11/09/2017			
☐ left monument as found ☐ lowere	d monument			
X On	On			
AND ON CENTERL	INE.			
SKETCH OF REFERENCE TIES				
SET 3/8" REBAR WITH REFERENCE CAP	SET 3/8" REBAR WITH PREFERENCE CAP 140TH STREET			
SET PK IN TOP OF POST N.T				
Statement of evidence for this corner location is on back of this page.				
I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.	Certified, Filed and or Recorded of March 08, 2018 8:23 AM			
Signature 15Wal.	W			
Signature 1/29/18 License No. 49563	NOBLES COUNTY RECORDER LYNN M. WILSON 507-295-5268			
Title:	Pages: 2			
X Land Surveyor Professional Engineer				
☐ County Surveyor ☐ County Engineer				

KRIS WROOLIE Minnesota License No. 49563

Statement of Evidence:

R-15

North Quarter Corner of Section 27, Township 104 North, Range 41 West, 5th Principal Meridian, Nobles County, Minnesota.

1868-Deputy Surveyor Richard N. L. Jeorlt, set a post in mound with pits for the section corner.

1936-Nobles County Highway Department "Corner Ties Book" calls for a stake at the corner location.

2017-On November 9th, Westwood Professional Services searched at E/W centerline and online with berm running south, found nothing. Set a 5/8" rebar capped 49563 equidistant between the NE and NW corners of Section 27 T.104 R.41 and slid to centerline. Position lands +/-5 ft. east of northerly berm extension. Ties were found or set as shown on the front of this certificate.

Analysis of the recovered data, field evidence and survey measurements, indicates that the monument found is the correct perpetuation of this corner. For additional information concerning this corner please contact Westwood Professional Services.

1,29/18