Jene	A TOWN	The SP
W_3	(是多种的	
Index _	V-9	sed

CERTIFICATE	OF LOCATION	OF GOV	ERNMENT	CORNER
NORTHEAST	Corner of Sectio	n <u>32</u> , 1	ownship 104N	, Ranae _41W
5th Principal Meridian, State				
At the corner location shown	on the sketch:			
On for	und			
☐ left monument as	found lowered	monument	removed	d monument (explain)
	aced a <u>5/8" REBAR CAPE</u> CENTERLINE INTERS	PED 49563 AT		
	CLIVIERLINE INTERS	SECTION		
	SKETCH OF REF	ERENCE TIES		
	KING AVE	N5504	SW CORNE ELECTRICAL I	
150TH STREE	ET			
CENTER OF GATE VALVE	SELL		NTER OF PEET SIGN	N.T.S.
Statement of e	evidence for this corner	location is	on back of this	
I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.			DOCUMI Certified, Man	EXT NUMBER A 3576 Filed and or Recorded ch 08, 2018 9:35 AM
Signature + Wal:			MF.	CLES COUNTY RECORDER
Signature 45 Wal: Date 1/29/18 Lice	ense No. 49563		1 72 ~ ' lan	LYNN M. WILSON 507-295-5268
Title:				Pages: 2
X Land Surveyor Profe	essional Fnaineer			
County Surveyor Coun	157			

KRIS WROOLIE Minnesota License No. 49563

Statement of Evidence:

V-9

Northeast Corner of Section 32, Township 104 North, Range 41 West, 5th Principal Meridian, Nobles County, Minnesota.

1868-Deputy Surveyor Richard N. L. Jeorlt, set a post in mound with pits for the section corner.

1900-Surveyor's Record Book A-2, page 382, prepared by County Surveyor M.S. Smith shows a stone at the corner location. Distance to the S1/4 of Sec. 28 T.104 R.41 is shown to be 2690.7 ft.

2017-On November 9th, Westwood Professional Services found nothing. Holding N/S/E/W centerline intersection as the best available evidence of the corner position. N/S/E/W centerline intersection agrees with the 1900 survey distances. Set a 5/8" rebar capped 49563 and set 3 ties.

Analysis of the recovered data, field evidence and survey measurements, indicates that the monument found is the correct perpetuation of this corner. For additional information concerning this corner please contact Westwood Professional Services.

129/18