Index	J-5
HIGEX	0 0

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER		
NORTHEAST Corner of Section	_18_ , Township _104N , Range _41W	
5th Principal Meridian, State of Minnesota, County of Nobles.		
At the corner location shown on the sketch:		
X On <u>11/29/2017</u> found a <u># 4 REBAR DOWN 0.3'.</u> DATE		
☐ lowered monument ☐ removed monument (explain)		
On placed a		
SKETCH OF REFERENCE TIES		
SET MAG IN W. END OF CMP	SET MAG IN E. END OF CMP	
a order - Comment of the comment of	120TH STREET	
SET MAG IN SE. FACE PP		
N.T.S. Statement of evidence for this corner location is on back of this page.		
I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of	DECUMENT NUMBER A 357576 Certified, Filed and or Recorded or March 07, 2018 3:25 PM	
Minnesota.	Lynn Wilson	
Signature ————————————————————————————————————	NOELES COUNTY RECORDER LYNN M. WILSON 507-295-5268	
Title:	Pages: 2	
	t ·	
☐ County Surveyor ☐ County Engineer	[

KRIS WROOLIE Minnesota License No. 49563

Statement of Evidence:

J-5

Northeast Corner of Section 18, Township 104 North, Range 41 West, 5th Principal Meridian, Nobles County, Minnesota.

1868-Deputy Surveyor set a post in mound with pits.

1896 - Nobles County Highway Department "Corner Ties Book" notes a stone marking the corner location.

1937 - Nobles County Highway Department "Corner Ties Book" notes a stone marking the corner location.

1939 - Nobles County Highway Department "Corner Ties Book" notes a stone marking the corner location and a wood stake placed.

2017 - Matthew Runke, LS 46171, files Certificate of Location as Document Number 354950 and gives measurements around section 17

2017-On November 29th, Westwood Professional Services recovered a #4 rebar down 0.3'. Adjacent measurements fit measurements on 2017 Runke survey. Ties were found or set as shown on the front of this certificate.

Analysis of the recovered data, field evidence and survey measurements, indicates that the monument found is the correct perpetuation of this corner. For additional information concerning this corner please contact Westwood Professional Services.