

Index C-25

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER		
EAST QUARTER Corner of Section 1 , Township 104N , Range 42W 5th Principal Meridian, State of Minnesota, County of Nobles. At the corner location shown on the sketch: \[\text{X} On \frac{12/06/2017}{DATE} \text{ found a } \frac{PK \text{ NAIL AND A TIE FROM 1994 TO THE CORNER FENCE POST.}} \]		
☐ On placed a	d monument	
SKETCH OF REFERENCE TIES SET 3/8" REBAR WITH REFERENCE CAP SET 3/8" REBAR WITH REFERENCE CAP SET 3/8" REBAR WITH REFERENCE CAP		
Statement of evidence for this corner	N.T.S.	
I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.	DDCUMENT NUMBER A 357474 Cartified, Filed and or Recorded on March 06, 2018 10:30 AM	
Signature	NOBLES COUNTY RECORDER LYDHIM. WILSON 507 295-5288 Pagas: 2	

KRIS WROOLIE Minnesota License No. 49563

Statement of Evidence:

C-25

East Quarter Corner of Section 1, Township 104 North, Range 42 West, 5th Principal Meridian, Nobles County, Minnesota.

1868-Deputy Surveyor set a post in mound with pits.

1894 - Nobles County Highway Department "Corner Ties Book" notes a stone set marking the corner location.

1923 - Nobles County Highway Department "Corner Ties Book" notes a stone marking the corner location.

1950 - Nobles County Highway Department "Corner Ties Book" notes a stone marking the corner location.

1951 - CSAH 13 highway plans show a station of 291+43 at this location. A distance of 2647.20 (per stationing) is given to the SE 1. No distance is given north to the NE 1.

1960 - Nobles County Highway Department "Corner Ties Book" notes stone marking the corner and a wood stake placed.

1980 - Nobles County Highway Department "Corner Ties Book" notes an iron pin marking the corner location.

1994 - Nobles County Highway Department "Corner Ties Book" notes a 1 3/4" PK nail set after an overlay. The following ties were made:

N/D in fence post N/D in power pole	West	51.96' 69.00'
	NW	
N/D in corner fence post	East	50.93

2017 - Westwood field crews recover a PK nail in the pavement and tie to the corner fence post from 1994. The pavement was not dug up due to the 1994 tie and monument. Measurements also fit within reason to 1951 CSAH13 highway plans. Ties were set or found as shown on the front of this certificate.

2/7/18