5'14 35 sec 35



Index \_\_\_\_A-19

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER		
NORTH QUARTER Corner of Section 2 , Township 103N , Range 42W		
5th Principal Meridian, State of Minnesota, County of Nobles.		
At the corner location shown on the sketch:		
X	On 12/05/17 found a PK ON CENTER	LINE AND A FENCE LINE TO THE NORTH
	X left monument as found	red monument
	On placed a	
	SKETCH OF R	EFERENCE TIES
	3	BEARINGS AND DISTANCES ARE BASE ON MINNESOTA STATE PLANE SOUTH COORDINATES
SE CORNER OF ELECTRIC BOX (2006)		
CSAH 16 S88-31-16E 2649.63		
	Mo 102	NE CORNER OF SECTION 2 (2006)
N.T.S.		NW CORNER OF TELEPHONE BOX (2006)
Statement of evidence for this corner location is on back of this page.		
resear direct	eby certify that this document was rched and prepared by me or under my supervision and that I am a licensed Land yor under the laws of the State of sota.	DOCUMENT NUMBER A 357382 Certified, Filed and or Recorded on February 28, 2018 11:50 AM
Signati	10/10 10507	Lynn Wilson
Signati Date _ Title:	ure + W.L.  1/8/18 License No. 49563	NOBLES COUNTY RECORDER LYNN MI. WILSON 507-295-5268
Date _ Title:	1/8/18 License No. 49563	NOBLES COUNTY RECORDER LYNN M. WILSON
Date	License No. 49563  Surveyor Professional Engineer  Sty Surveyor County Engineer	NOBLES COUNTY RECORDER LYNN MI. WILSON 507-295-5268

## KRIS WROOLIE Minnesota License No. 49563

## Statement of Evidence:

A-19

North Quarter Corner of Section 2, Township 103 North, Range 42 West, 5<sup>th</sup> Principal Meridian, Nobles County, Minnesota.

1869-Deputy Surveyor set a post in mound with pits.

1901- Nobles County Highway Department "Corner Ties Book" calls for a stone to mark the corner location.

1922- Nobles County Highway Department "Corner Ties Book" calls for a stone to mark the corner location.

1943- Nobles County Highway Department "Corner Ties Book" calls for a stone to mark the corner location.

1967- Nobles County Highway Department "Corner Ties Book" calls for a pipe and a placed iron rod to mark the corner location.

2006 - Ulteig Engineers found a 5/8" rebar at the road centerline and a fence line to the north, set ties, and file a Certificate of Location doc. no. 311285

2016 - County Highway Department set a PK nail after an overlay

2017- Westwood Professional Services recovered a PK nail with a magnetic indication under it on centerline and fence line to the north, and one ties from the 2006 Certificate. Accepting as the best available evidence for the corner. Ties were found or set as shown on the front of this certificate