

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER	
NORTHEAST Corner of Secti	on <u>20</u> , Township <u>104N</u> , Range <u>42W</u>
5th Principal Meridian, State of Minnesota, County of Nobles.	
At the corner location shown on the sketch:	
On 11/29/2017 found a PIPE WITH AND ILLEGIBLE CAP DOWN 0.3' AT CENTERLINE INTERSECTION.	
☐ left monument as found ☐ lowere	ed monument
On placed a	
SKETCH OF REFERENCE TIES	
n.	
A A	9 4 g = 2 ⁹⁰ 4
SE. CORNER OF ELECTRICAL BOX	SW. CORNER OF E ELECTRICAL BOX
SE. CORNER OF ELECTRICAL BOX	08
- No. 34 - No. 34 -	
130TH STREET	
	STREET SIGN
N.T.S. Statement of evidence for this corner location is on back of this page.	
	l sur sur sur sur page.
I hereby certify that this document was researched and prepared by me or under my	DOCUMENT NUMBER A 357507
direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota	Certified, Filed and or Recorded on
Minnesota. March 06, 2018 3:05 pM	
Signature + W.	Lynn Wilson
Date 2/7/18 License No. 49563	NOBLES COUNTY RECORDER LYNN M. WILSON 507-295-5268
Title:	Pages: 2
X Land Surveyor Professional Engineer	
☐ County Surveyor ☐ County Engineer	

KRIS WROOLIE Minnesota License No. 49563

Statement of Evidence:

N-9

Northeast Corner of Section 20, Township 104 North, Range 42 West, 5th Principal Meridian, Nobles County, Minnesota.

1868-Deputy Surveyor set a post in mound with pits

1894- Nobles County Highway Department "Corner Ties Book" calls for a stone set to mark the corner location.

1901- Nobles County Highway Department "Corner Ties Book" calls for a stone to mark the corner location.

1932- Nobles County Highway Department "Corner Ties Book" calls for a stone to mark the corner location.

2017- Westwood Professional Services recovered an illegible capped pipe at the centerline intersection. Ties were found or set as shown on the front of this certificate.

Analysis of the recovered data, field evidence and survey measurements, indicates that the monument found is the correct perpetuation of this corner. For additional information concerning this corner please contact Westwood Professional Services.

2/7/18