

Index ____C-21

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER	
EAST QUARTER Corner of Section 2 , Township 104N , Range 42W 5th Principal Meridian, State of Minnesota, County of Nobles.	
At the corner location shown on the sketch:	
X On <u>11/28/2017</u> found a <u>DNR 5/8" REBAR CAPPED 19839 DOWN 0.4'.</u>	
🗵 left monument as found 🗌 lowered monument 🗍 removed monument (explain)	
On placed a	
SKETCH OF REFERENCE TIES FOUND NAIL AND N86°E WASHER IN W. FACE FENCE POST (2006) N87E 29.77 FOUND FACE OF DNR SIGN (2006) SET 3/8" REBAR N.T.S.	
Statement of evidence for this corner location is on back of this page.	
I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.	DEFOURTMENDMENT & 357476 Cardined, Filed and or Recorded on March 06, 2019 10:40 ATT
Signature +5 No. 2/1/18 Date 2/1/18 License No. 49563 Title:	MORLES COUNTY RECORDER LYCRI M. WILSON 507-295-5258
	Pages: Z
☐ County Surveyor ☐ County Engineer	

KRIS WROOLIE Minnesota License No. 49563

Statement of Evidence:

C-21

East Quarter Corner of Section 2, Township 104 North, Range 42 West, 5th Principal Meridian, Nobles County, Minnesota.

1868-Deputy Surveyor set a post in a mound with pits for the corner.

1971 - MN DNR shows the corner in place with a distance of 2726.76 to the NE corner of section 2 and a distance of 5315.59 to the E1/4 of section 1

1979- Nobles County Highway Department "Corner Ties Book" calls for a railroad spike to mark the corner location.

2006 - Ulteig Engineers found a hexagonal bar on centerline and fences to the east and west, set ties, and file a Certificate of Location doc. no. 311291

2017- Westwood Professional Services recovered a rebar with a LS cap DNR 19839 and 2 ties from the 2006 COL. Ties were found or set as shown on the front of this certificate

Analysis of the recovered data, field evidence and survey measurements, indicates that the monument found is the correct perpetuation of this corner. For additional information concerning this corner please contact Westwood Professional Services.

2/1/2