No. of the last		E TOTAL TO	TOTA AND
The state of the s		Day.	
	1000	ika	26

Index L-21

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER					
EAST QUARTER Corner of Sect	ion <u>14</u> , Township <u>104N</u> , Range <u>42W</u>				
5th Principal Meridian, State of Minnesota, County of Nobles.					
At the corner location shown on the sketch:					
X On 12/27/2017 found NO EVIDENCE.					
☐ left monument as found ☐ lowere	Terroved monament (explain)				
X On <u>12/27/2017</u> placed a <i>1/2" REBAR CAF</i>	On <u>12/27/2017</u> placed a <i>1/2" REBAR CAPPED RLS 49563 0.4' DOWN AT LOST POSITION</i> DATE				
SKETCH OF REFERENCE TIES					
	*				
SEL MAC IN C. FACE IN					
SET MAG IN S. FACE IN FIBER OPTIC SIGN					
xx <u>- N88'W</u> Q	S87'Exxxxx				
1,0	4				
A 72 72 72 72 72 72 72 72 72 72 72 72 72 72					
	8				
SM07134	SET 3/8" REBAR WITH REFERENCE CAP				
	4				
Statement of avidence for the	N.T.S.				
Statement of evidence for this corner location is on back of this page.					
I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land	DOCUMENT NUMBER A 357489 Certified, Filed and or Recorded on				
Surveyor under the laws of the State of Minnesota.	March 06, 2018 11:45 AM				
Signature <u>+5/Val.</u> Date <u>2/7/18</u> License No. 49563	Lynn Willson				
Date 2/7/18 License No. 49563	NOBLES COUNTY RECORDER LYNN M. WILSON 507-295-5268				
Title:	Pagas: 2				
☐ County Surveyor ☐ County Engineer	1				

KRIS WROOLIE Minnesota License No. 49563

Statement of Evidence:

L-21

East Quarter Corner of Section 14, Township 104 North, Range 42 West, 5th Principal Meridian, Nobles County, Minnesota.

1868-Deputy Surveyor set a post in mound with pits

1836- Nobles County Highway Department "Corner Ties Book" calls for a stone to mark the corner location.

2006 - Ulteig Engineers set a 5/8" rebar capped 44563 midway and online between section corners, set ties, and filed a Certificate of Location doc. no. 311316

2017 - Westwood Professional Services did not recover any evidence of the corner. A 5/8" rebar capped LS 49563 was placed midway and online between section corners to mark the quarter corner. Ties were found or set as shown on the front of this certificate.

Analysis of the recovered data, field evidence and survey measurements, indicates that the monument found is the correct perpetuation of this corner. For additional information concerning this corner please contact Westwood Professional Services.