15 m/h 200 /21 42



X-5 Index _

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER	
EAST QUARTER Corner of Secti	on <u>31</u> , Township <u>104N</u> , Range <u>42W</u>
5th Principal Meridian, State of Minnesota, County of Nobles.	
At the corner location shown on the sketch:	
X	
☐ left monument as found ☐ lowered monument ☐ removed monument (explain)	
On 12/27/2017 placed a 1/2" REBAR CAPI BATE RUNNING EAST.	PED LS 49563 DOWN 0.4' ON CENTERLINE AND FENCE
SKETCH OF REFERENCE TIES	
SET 3/8" REBAR WITH REFERENCE CAP N.T.S.	
Statement of evidence for this corner location is on back of this page.	
I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.	Certified, Filed and or Recorded on March 07, 2018 9:35 AM
Signature TS Wal.	Lynn Wilson
Signature	NOBLES COUNTY RECORDER LYNN M. WILSON 507-295-5268
Title:	Pages: 2
☐ County Surveyor ☐ County Engineer	

KRIS WROOLIE Minnesota License No. 49563

Statement of Evidence:

X-5

East Quarter Corner of Section 31, Township 104 North, Range 42 West, 5th Principal Meridian, Nobles County, Minnesota.

1868-T.B. Walker set a post in mound with pits for the section corner.

1910- Nobles County Highway Department "Corner Ties Book" calls for a stone to mark the corner location.

1934- Nobles County Highway Department "Corner Ties Book" calls for a stone to mark the corner location.

2017- Westwood Professional Services located a north/south centerline and a fence line to the east. This long standing occupation agrees closely with the proportional position between adjacent section corners and is accepted as the best available evidence for the corner. A 5/8" rebar capped 49563 was placed on centerline and the fence line to the east to mark the corner. Ties were set as shown on the front of this certificate.

Analysis of the recovered data, field evidence and survey measurements, indicates that the monument found is the correct perpetuation of this corner. For additional information concerning this corner please contact Westwood Professional Services.

7=5 Mace