DOCUMENT NUMBER A 306812

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER	
South 1/4Corner of Section15, Township102N, Range39W, 5th_ P.M.	
STATE OF MINNESOTA, County of Nobles	
At the corner location shown on the sketch	
On 9/21/05 found a 60d spike at road surface, excavated below and found 3/4"	
iron pipe 2' deep and on road centerline.	
left monument as found lowered monument, removed monument (explain)	
On 9/21/05 placed a 1" iron pipe with red survey cap #43803 over top of iron pipe.	
Onpidced d	
SKETCH OF F	REFERENCE TIES
4	
INIS RAY ES	
-N- OF TICENSE E	·
43803	
	STEEL UTILITY WARNING POST
OF MINNES	√
0	<i>→</i> 51.25
200TH 🔏	ST.
83.48 \	
NAIL & DISK	NAIL & DISK IN
IN POWERPOLE	WOOD CORNER POST
FENCE	
*	NAD 83 (1996)
	US STATÈ PLANE 1983 MN SOUTH
	561691.79N 2226786.70E
Statement of evidence relative to this corner location is on page 2.	
Lite to the decrease and the data	OFFICE OF THE COUNTY RECORDER
I hereby certify that this document and the data contained herein was prepared by me or under my	OFFICE OF THE OCCUPANT NECONDER
direct supervision.	I hereby certify that this document was filed in
Dennis Kan Laplan 10/29/05 SIGNATURE O DATE	the Co. Recorder's Office at on the
MN. LICENSE NO43803	day of
🗵 Land Surveyor, 🗌 Professional Engineer	County Recorder
	By, Deputy
County Surveyor, L County Engineer	DOCUMENT NO

Statement of Evidence

1868 Original Township Subdivision was surveyed by Jewett & Howe.

1913 Nobles Co. Hwy. Dept. records indicate a stone was found.

1959 Nobles Co. Hwy. Dept. records indicate an iron pin was found.

2005 Gerald Vickerman PLS and Jeremy Lund, with Zieske Land Surveying, found a 60d spike at road surface, excavated below and found a 3/4" iron pipe, 2' deep on centerline of road.

DOCUMENT NUMBER A 306812

Certified, Filed and or Recorded on NOV. 07, 2005 AT 03:40:00PM

TRACKED COMPARED PHOTO FEE

NOBLES COUNTY RECORDER LYNN M. WILSON 507-372-8216