# # Total		3,43995 1,449 1,449 1,449	The state of the s
Index	V-1	7	RESS.

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER			
NORTHEAST Corner of Section	n <u>34</u> , Township <u>104N</u> , Range <u>41W</u>		
5th Principal Meridian, State of Minnesota, County o			
At the corner location shown on the sketch:			
X On <u>11/08/2017</u> found a <u>5/8" REBAR AT TH</u>	HE CENTERLINE INTERSECTION		
☐ Iowered	monument  removed monument (explain)		
Onplaced a	*		
SKETCH OF REFERENCE TIES			
FOUND NAIL AND BOTTLE CAP IN PP  (1978)			
FOUND NAIL AND BOTTLE CAP IN PP (1978)	SET PK IN TOP CORNER POST  N.T.S.		
Statement of evidence for this corner location is on back of this page.			
I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.	DOCUMENT NUMBER A 357508 Certified, Filed and or Recorded on March 08, 2018 10:10 AM  Lynn Lilbary		
Signature 15/16  Date 1/29/18  License No. 49563	NOBLES COUNTY RECORDER LYNN M. WILSON 507-295-5268 Pages: 2		
Title:			
☐ County Surveyor ☐ County Engineer			

## KRIS WROOLIE Minnesota License No. 49563

## Statement of Evidence:

V-17

Northeast Corner of Section 34, Township 104 North, Range 41 West, 5<sup>th</sup> Principal Meridian, Nobles County, Minnesota.

1868-Deputy Surveyor Richard N. L. Jeorlt, set a post in mound with pits for the section corner.

1936-Nobles County Highway Department "Corner Ties Book" calls for a stone at the corner location.

1978-Nobles County Highway Department "Corner Ties Book" calls for a stone at the corner location. Placed iron pin.

Ties:

N&D IN PP N.W. 54.42'

N&D IN PP S.E. 34.15'

N&D IN PP S.W. 46.95'

2017-On November 8th, Westwood Professional Services found a No. 5 rebar and 2 of the 3 Nobles County Highway Department ties, which fit. Monument fits GLO distance to the NE corner of Sec. 35 T.104 R.41 within 1 foot. Accepting the found No. 5 rebar as the position of the corner and set 1 additional tie.

Analysis of the recovered data, field evidence and survey measurements, indicates that the monument found is the correct perpetuation of this corner. For additional information concerning this corner please contact Westwood Professional Services.