GUPY

CERTIFICAT

CENTIFICATE OF LOCATION OF GOVERNMENT CORNER	
EAST QUARTER Corner of Section	ion <u>31</u> , Township <u>104N</u> , Range <u>41W</u>
5th Principal Meridian, State of Minnesota, County of Nobles.	
At the corner location shown on the sketch:	
X On 11/09/2017 found NOTHING	
☐ left monument as found ☐ lowered monument ☐ removed monument (explain)	
X On 12/29/2017 placed a <u>5/8" REBAR CAPPED 49563 ON CENTERLINE AND FENCE LINES TO THE</u> EAST AND WEST	
SKETCH OF REFERENCE TIES	
FIRST T-POST ON FENCE LINE 31.62' A ME A ME	SET PK IN PP SET PK IN PP SET \$\frac{3}{6}.00^{7} - \frac{3}{6}.00^{7}
1 -	N.T.S.
I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.	DOCUMENT NUMBER A 357597 Certified, Filed and or Recorded on March 08, 2018 9:15 AM
Signature 1/29/18 Date 1/29/18 License No. 49563	NOBLES COUNTY RECORDER LYNN M. WILSON 507-295-5268 Pages: 2
X Land Surveyor ☐ Professional Engineer	
☐ County Surveyor ☐ County Engineer	

KRIS WROOLIE Minnesota License No. 49563

Statement of Evidence:

X-5

East Quarter Corner of Section 31, Township 104 North, Range 41 West, 5th Principal Meridian, Nobles County, Minnesota.

1868-Deputy Surveyor Richard N. L. Jeorlt, set a post in mound with pits for the section corner.

2017-On November 9th, Westwood Professional Services searched a N/S road centerline and online with fence line running east and a fence line running west and found nothing. The local longstanding occupation agrees closely with record distances and is accepted as the best available evidence for the corner. A 5/8" rebar capped 49563 was placed on the N/S centerline and on line with fence lines running east and west to mark the corner. Ties were set as shown on the front of this certificate.

Analysis of the recovered data, field evidence and survey measurements, indicates that the monument found is the correct perpetuation of this corner. For additional information concerning this corner please contact Westwood Professional Services.

1/59/18