

Index V-3

CERTIFICATE (OF LOCATION	OF GOVERNME	NT CORNER	
NORTH QUARTER	Corner of Section	on <u>31</u> , Township <u>1</u>	104N , Range <u>4</u>	2W
5th Principal Meridian, State of				
At the corner location shown o	n the sketch:			
On	d a <i>NOTHING</i> .			
☐ left monument as f	ound	d monument	noved monument (e	xplain)
	ed a <u>1/2" REBAR CAPF</u> AGREES WITH 191	PED LS 49563 DOWN 0.4' A O SURVEY	T LOST POSITION WHIC	<u> </u>
	SKETCH OF REI	FERENCE TIES		
3		CET 7/0	" DEDAR WITH	
			" REBAR WITH RENCE CAP	
	٠	N755-		l
	a:W		*1L 1L	
	<u> </u>	107	150TH STREET	4
SET 3/8" REBAR WITH of		5005		
REFERENCE CAP				-N-
		SET 3/8" REFERI	REBAR WITH ENCE CAP	
				N.T.S.
Statement of ev	dence for this corne	r location is on back of	f this page.	
I hereby certify that this doct researched and prepared by n direct supervision and that I i Surveyor under the laws of th Minnesota.	ne or under my am a licensed Land e State of	Cert	CUMENT NUMBER ified, Filed and or I March 07, 2018 9	:40 AM
Signature + 1 / Licen Date 2/7/18 Licen			Lynn Wi	lan
Date <u>2/7/18</u> Licen	se No. <u>49563</u>		NOBLES COUNTY RE	ECORDER
Title:			LYNN M. WILS 507-295-52	2014
🛮 Land Surveyor 🔲 Profes	sional Engineer			
□ County Surveyor □ County	/ Engineer			

KRIS WROOLIE Minnesota License No. 49563

Statement of Evidence:

V-3

North Quarter Corner of Section 31, Township 104 North, Range 42 West, 5th Principal Meridian, Nobles County, Minnesota.

1868-T.B. Walker set a post in mound with pits for the section corner.

1910- Nobles County Highway Department "Corner Ties Book" calls for a stone set proportionally to mark the corner location.

2017- Westwood Professional Services located an east/west centerline. The overall distance along the north line of the section agrees closely to the 1910 survey distances. A 5/8" rebar capped 49563 was place online between section corners and at the proportional distance from the 1910 survey. Ties were set as shown on the front of this certificate.

Analysis of the recovered data, field evidence and survey measurements, indicates that the monument found is the correct perpetuation of this corner. For additional information concerning this corner please contact Westwood Professional Services.

7-51 WC=