

Index ____J-11

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER	
NORTH QUARTER Corner of Section	16 , Township <u>104N</u> , Range <u>42W</u>
5th Principal Meridian, State of Minnesota, County of Nobles.	
At the corner location shown on the sketch:	
☐ left monument as found ☐ lowered monument ☐ removed monument (explain)	
X On 12/27/2017 placed a 1/2" REBAR CAPPED 49563 DOWN 0.4'. MIDWAY BETWEEN SECTION DATE CORNERS AND ON CENTERLINE	
SKETCH OF REFERENCE TIES	
SET 3/8" REBAR WITH REFERENCE CAP	
۵	SET 3/8" REBAR WITH REFERENCE CAP
N76 E 0	
1	
SET MAG E. END OF 24" CMP	
N.T.S. Statement of evidence for this corner location is on back of this page.	
I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.	DDCUNE RT MUMBER A 357 491 Certified, Filed and or Recorded o March 06, 2018 2:56 PM
Signature <u> </u>	Lynn Wilson
Date 2/7/18 License No. 49563	NOBLES COUNTY RECORDERS LYNN M. WILSON 507-295-5268
Title:	Pages: 2
🛮 Land Surveyor 🔲 Professional Engineer	,
☐ County Surveyor ☐ County Engineer	

KRIS WROOLIE Minnesota License No. 49563

Statement of Evidence:

J-11

North Quarter Corner of Section 16, Township 104 North, Range 42 West, 5th Principal Meridian, Nobles County, Minnesota.

1868-Deputy Surveyor set a post in mound with pits

1894- Nobles County Highway Department "Corner Ties Book" calls for a stake to mark the corner location.

1900- Nobles County Highway Department "Corner Ties Book" calls for a stone to mark the corner location.

2017- Westwood Professional Services located centerline and field lines to the north and south which agrees close to the proportionate position. A 5/8" rebar capped 49563 was placed midway between section corners and on centerline to mark the quarter corner. Ties were set as shown on the front of this certificate.

Analysis of the recovered data, field evidence and survey measurements, indicates that the monument found is the correct perpetuation of this corner. For additional information concerning this corner please contact Westwood Professional Services.

= 15/WE