ndex	No	100

	Index No.
CERTIFICATE OF LOCATION	OF GOVERNMENT CORNER
NORTHFAST Corner of Section 6	_, Township <u>101</u> , Range <u>40</u> , 5th P.M.
STATE OF MINNESOTA, County of NOBLES	
At the corner location shown on the sketch:	
\boxtimes On 6-6-07 found a 1/2" IRON PIPI	E 6" BELOW SURFACE ABOVE
GRAY STONE 36" DEEP WITH LARG	
☑ left monument as found, ☐ lov	vered monument, \square removed monument (exploin) NW CORNER OF STONE & SET PLS MnDOT
CAP ON A 24" UNISTRUT ABOVE ST	The state of the s
SKEICH OF RI	EFERENCE TIES
NORTHEAST CORNER SECTION 6-T101N-R40W PLS MnDOT CAP ON A 24" UNISTRUT ABOVE STONE 280th St GRAVEL ROAD SRP NN PP SECTION 6-101-401	WASTONE TEL PED POST By NORTH 1/4 CORNER SECTION 5-T101N-R40W STONE 2658.96' (meas) 2658.1 (1911) Street Sign Post SECTION 5-101-40
NAD83 (1996 ADJUSTMENT) STATE PLANE COORDINATES NOBLES COUNTY DATUM N= 131978.100 E= 573281.703	EAST 1/4CORNER SECTION 6-T101N-R40W PLS MnDOT CAP ON 30" UNISTRUT ABOVE ROTTED WOOD STAKE BK. 333 PG. I:\MnDT\M3239399\Cod\certs\NEC06-101-
Statement of evidence relative to this corn	× × × × × × × × × × × × × × × × × × ×
I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision. 6-35-3007 JOSEPH A. HAEPNER DATE	OFFICE OF THE COUNTY RECORDER County of I hereby certify that this document was fil in the Co. Recorders office atM. on the day of A.D., 20_
Registration No. 43909	County Recorder
□ Professional Engineer	By, Deput
☐ County Surveyor, ☐ County Engineer	DOCUMENT NO.

Statement of Evidence

Northeast Quarter Corner Section 6, Township 101 North, Range 40 West

1867

-Thomas B. Walker, U.S. Deputy Surveyor, his notes read: "East Random Line Between Towns 101 & 102, Range 40." I set temporary corners along line & at intersect town line 15.50 chs north of corner." "Upon examination; I find my instrument grossly our of repair & adjustment" "Declination Bar badly bent by shutting the box cover on it, telescope axis askew as also telescope sights." "As my line cannot be straight, I now sure west Random line & at a point 130 lks. North of Town Corner." "My correction will be 21.23 lks south per mile, the excess remaining at the west end." "S 89° 51' E between Sections 6 & 31, Var 11°15' E," @ 41.23 chs "1/4 Coner Post in Mound", no ties

27 Apr. 1911

-Nobles County Recorder's Office, Surveyor's Record, Volume B. Page 12, by William A. Saxon, County Surveyor, for a survey of Section 32-102-40, states "Found a stone at the NE Corner of Sec 6 in Bigelow Township, with a cross mark cut in it, but found no record of this stone" "also found an iron bolt at this corner about 2 1/2 feet west of the stone" "I discarded the bolt and used the stone as the corer, as it tallied more nearly with the measurements" a distance of east 2658.1' is shown to the corresponding quarter section corner, ties are shown as follows: Tel Pole - 69' NE

Stump - 46' SW

1931

Nobles County Highway Department records state a stone was found, at this corner.

1935

Nobles County Highway Department records state a stone was found, at this corner.

1969

Nobles County Highway Department records state a 2X2 hub found at this corner and 1/2' x 24" iron pipe was placed.

1978

Nobles County Highway Department records state an iron pin was found, at this corner,

ties are shown as follows:

Nail & Disk Cor Fence Post - 56.84 SE Nail & Disk in Power Pole - 41.63 SW Nail & Disk in Power Pole - 41.31' NW Nail & Disk in UTC MRK - 44.25 NE

9 May 2007

-Bolton & Menk, Inc., survey crew survey crew found a ½" x 24" iron pipe 6" below gravel surface (removed during excavation) on top of a gray granite stone with an "X", 36" below the gravel surface. Distance of east 2658.96' and south 2731.00' was measured to the corresponding quarter corners.

21 June 2007

-Bolton & Menk, Inc., survey crew set a PLS MnDot Cap on a 24" Unistrut on top of the above referenced stone.

This evidence is conclusive back to the 1911 survey by Saxon. The evidence does not tie the original stake to the stone; however the stone is the best evidence of the true corner location. Additional information regarding the preparation of this certificate can be obtained by contacting: Bolton & Menk, Inc., 219 North Main Street, Fairmont, MN 56013.