245399

Index No. _____

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

EAST QUARTER Corner of Section 36, Township 101, Range 41W, 5 P.M.

STATE OF MINNESOTA, County of NOBLES


At the corner location shown on the sketch:

☒ On Oct. 29, 1980 (DATE) found a 20 inch by 24 inch by 4 inch Limestone rock, down 1.0 feet. Use highest point for measurement.

☒ left monument as found, ☐ lowered monument, ☐ removed monument (explain)

☐ On _____ (DATE) placed a _____

SKETCH OF REFERENCE TIES



Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

S. Eldon Lobb (SIGNATURE) 2-4-83 (DATE)

Registration No. 11933

☒ Land Surveyor, ☐ Professional Engineer

☐ County Surveyor, ☐ County Engineer

OFFICE OF THE COUNTY RECORDER
County of Nobles

I hereby certify that this document was filed in the Co. Recorders, office at 4:30 P.M. on the 16th day of September A.D., 1991

County Recorder Joyce Howard

By _____, Deputy

DOCUMENT NO. 245399

Mn/DOT 2105 (4-77)

245399

Statement of Evidence: East Quarter Corner Section 36, Township 101N Range 41 W 5 P.M.

Apr. 17, 1867 — Thomas B. Walker, Original Public Land Surveyor, notes read. "Set $\frac{1}{4}$ Sec. Cor. post in mound."

1914 — Nobles County Highway Department notes state that a stone was set.

June 25, 1917 — William A. Saxon, County Surveyor, did a survey in Section 31, Township 101N, Range 40W. His notes read, "found stone at $W\frac{1}{4}$ cor. Distance of 2652 feet to land corner south, and 2733 feet to land corner north.

1935 — Minnesota Highway Department Right of Way print indicates East Quarter corner of Section 36 is 879.0 feet west of P.O.T. Sta. 28+39.4.

Oct. 29, 1980 — Minnesota Department of Transportation survey crew found 20 inch by 24 inch by 4 inch limestone rock down 1.0 feet. Tractor backhoe was used for excavating. The monument is on east-west fence line and north fence line.

The inplace location of the 20 inch by 24 inch by 4 inch limestone rock is compatible with the occupation lines within the section. An analysis of the Statement of Evidence and the field measurements indicate that the limestone rock is in a reasonable location. I therefore accept the monument as the location of the land corner.

For additional information, including field measurements and photographs, contact the Minnesota Department of Transportation in Windom.

Tract B.L. Compared
Photo B.L.
Fee XX