CERTIFICATE OF LOCATION OF GOVERNMENT CORNER		
NORTH QUARTER Corner of Section 4 , Township JO2N , Range 39W , 5 th P.M. STATE OF MINNESOTA, County of NOBLES		
At the corner location shown on the sketch:		
On Nov. 3, 1989 found a 8 inch by 14 inch by 18 inch stone down about 3 feet below surface. Definate high point of stone not up. Stone questionable as left monument as found, lowered monument, removed monument (explain) corner location. On Dec. 22, 1992 placed a Minnesota Department of Transportation Cast Iron DATE Monument approximately 10 feet south of centerline of dirt road and 2 feet		
SKETCH OF REFERENCE TIES below surface.		
SECTION 3	3–103–39	
- N -		
CULTIVATED		
Minimum Maintenance Road (No Ditches) 10 foot dirt surface		
STONE		
CULTIVATED	NO REFERENCE TIES	
SECTION 4-102-39	SECTION 4-102-39	
Statement of evidence relative to this corner location is on back of page.		
I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision. **Discount Control of the data o	OFFICE OF THE COUNTY RECORDER County of Ables I hereby certify that this document was filed in the Co. Recorders office at E. D. A. M. on the 20theray of A.D., 1923 County Recorder A.D., 1923	
☑ Land Surveyor, ☐ Professional Engineer ☐ County Surveyor, ☐ County Engineer	By	

Mn/DOT 2105 (4-77)

250855 Statement of Evidence: North Quarter Corner of Section 4, T102N, R39W, 5th P.M.	
June 24, 1896	M. S. Smith, Nobles County Surveyor, did a survey in Section 4 and his survey plat indicates $\frac{1}{4}$ post in mound.
Nov. 3, 1989	A Minnesota Department of Transportation crew chief, Roger Busse, and crew dug for the corner with a backhoe. They dug a hole 12 feet east, 5 feet south, 4 feet north and 9 feet west of the computed lost location to a depth of approximately 3 feet. The trench covered a possible occupation line to the south which is approximately 6 feet east of the lost location. The lost location is about 7 feet south of the centerline of a road. They found no evidence of an original stake, but did find a stone in the southwest side of the hole.
Nov. 6, 1989	A Minnesota Department of Transportation crew chief, Roger Busse, and crew placed a 3/4 inch diameter by 24 inch iron pin over the stone and $1\frac{1}{2}$ feet below the road surface with a 60 penny spike on the surface.
Dec. 22, 1992	A Minnesota Department of Transportation survey crew consisting of Deni Ernst and Deni Janke, placed a Minnesota Department of Transportation Cast Iron Monument at a lost location site computed from other established corners.
	The lack of record and field evidence indicates that this corner be set by lost methods, midway and on line between section corners.
	For additional information contact the Minnesota Department of Transportation in Windom.
	、