CERTIFICATE OF LOCATION	OF GOVERNMENT CORNER
NORTHEAST Corner of Section 15	,Township $102N_{\odot}$ , Range $40W_{\odot}$ , $5_{\odot}$ P.M.
STATE OF MINNESOTA, County ofNOBLES_	,
At the corner location shown on the sketch:	
Stone Down 18", Pin Over Center of I	Down 0.3', Wood Stakes Down 15",  Flat Stone. ed monument,   removed monument (explain)
□ Onplaced a	
2'West of Center- line of North/South Township Road and 3' North of Center- line of East/west Township Road.  SECTION 10	township road  Section  Sectio
 18 foot gravel surface township road	72 43
Copper Nail in Disc(SRP) in Southeast Side of Power Pole up 2 feet.	Copper Nail in Disc(SRP) in East Side of Telephone Pedestal Post up 3 feet.  73.96 Copper Nail in Disc(SRP) in Northeast Side of Power Pole up 3 feet.
SECTION 15	SECTION 14
Statement of evidence relative to this corner location is on back of page.	
I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.	OFFICE OF THE COUNTY RECORDER  County of
☐ County Surveyor ☐ County Engineer	DOCUMENT NO. 203808

28.

Mn/DOT 2105 (4-77)

## Statement of Evidence:

N.E. Cor. Sec. 15 TlO2N R40W Nobles

- September 25, 1868 George G. Howe The original Public Land Surveyor's notes read: "Set post in mound with pits for corner to Sections 10, 11, 14 & 15".
- April 30, 1894 Milton S. Smith County Surveyor, did a survey in Section 10 and "Found original stake-set stone" at the S.E. Cor. Section 10.
- 1894 Nobles County Highway Department's note for S.W. Corner Section 11 read: "Stone in 1894 set".
- November 8, 1902 M. S. Smith, County Surveyor, did a survey in Section 14 and certifies a "Stone" at the N.W. corner.
- 1903 Nobles County Highway Department's note for S.W. corner Section 11 read: "Stone in 1903".
- 1940 Nobles County Highway Department's note for S.W. corner Section 11 read: "Stone in 1940".
- 1959 Nobles County Highway Department's note for S.W. corner Section 11 read: "Stake in 1959 placed Iron Pin".
- April 13, 1960 E. Polesky Minnesota Highway Department's Survey crew for S.P. 5380 T.H. I-90 "Found 1 x 2 down 2.5' ". Placed 5/8 inch iron pin over down 0.3 feet.
- February 22, 1978 Foster, Stoeckman and Verdoorn of the Minnesota Department of Transportation used notes from Location Survey S.P. 5380-01. Found 5/8 inch iron pin down 0.3 feet.
- March 28, 1978 David Raley of the Minnesota Department of Transportation contacted the following people in the area of this land corner: James Kramer age 60± and Bob Hansen age 60±. Bob Hansen advised that there should be an iron stake and rock at this location. Other than this information, neither knew of any surveys, property disputes, or anything else about this land corner. Mr. Hansen has lived in the area all his life, and Mr. Kramer has lived here 12 years.

An analysis of the Statement of Evidence and the field measurements indicate that the inplace location of the iron pin, wood stake, and stone provides a continuous chain of perpetuation of the original Public Land Survey corner.

For additional information, including field measurements and photographs, contact the Minnesota Department of Transportation in Windom.