Index No. _____

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

EAST 1/4 Corner of Section 24, Township 102, Range 40, 5th P.M.

STATE OF MINNESOTA, County of NOBLES


At the corner location shown on the sketch:

☒ On 6-5-07 (DATE) found a 2 1/2" ALUMINUM CAP IN BIT. ROADWAY (AT SURFACE)

☒ left monument as found, ☐ lowered monument, ☐ removed monument (explain)

☐ On _____ (DATE) _____

SKETCH OF REFERENCE TIES



NAD83 (1996 ADJUSTMENT)
STATE PLANE COORDINATES
NOBLES COUNTY DATUM

N= 145262.948

E= 599691.896

BK. 333 PG. 11

I:\MnDT\M3239399\Cad\certs\EQ24-102-40

Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

JOSEPH A. HAEFNER — DATE 6/7/2007

Registration No. 43909

☒ Land surveyor, ☐ Professional Engineer

☐ County Surveyor, ☐ County Engineer

OFFICE OF THE COUNTY RECORDER

County of _____

I hereby certify that this document was filed in the Co. Recorders office at ___.M. on the _____ day of _____ A.D., 20___

County Recorder _____

By _____, Deputy

DOCUMENT NO. _____

Statement of Evidence

East Quarter Corner Section 24, Township 102 North, Range 40 West

1867	-T.B. Walker, U.S. Deputy Surveyor, his notes read: "North between sections 24 & 19, Var. 11°30'E" @ 40.00 chs " set post in mound with pits for quarter section corner", no ties
23 Apr 1892	-Nobles County Recorder's Office, Surveyor's Record, Volume A-2, by Milton S. Smith, County Surveyor, for a survey in Section 24, states "1/4 post on east line is a stone" "don't know who set it but corresponds exactly with W Shepard's subdivision in section 24 and by running an extended line from west ¼ post and center post"
1963	-Nobles County Highway Department records show an iron pin at this corner.
13 Sep 1982	- Northland Engineers & Surveying, Inc., File No. 82011, Recorded as Document No. 215480, for a survey of Chichago, Rock Island & Pacific Railroad Monumentation, states "found monument (3/4" iron pipe w/cap no. 5094)"
15, May 1980	-Minnesota Department of Transportation, survey crew, found a ¾" pipe with plastic cap stamped RLS 5094, flush with bituminous surface and in center of County Road 5.
13 June 1995	-Madsen Land Surveying Inc., Survey File No. 9595, for a survey in Section 19-102-39, states "found a ½" iron rod in bituminous pavement (surface)" for the West Quarter of Section 19 (East Quarter Section 24)
29 Apr 1998	City of Worthington GPS survey, "found 5/8" iron pipe; set alum cap over iron rod"
7 July 2004	-Madsen Land Surveying Inc., Survey File No. 04082, for a survey in Section 24, states "5/8" iron monument with an aluminum cap in bituminous paving (surface)"
5 June 2007	-Bolton & Menk, Inc., survey crew found a 2 ½" Aluminum Cap at the surface of concrete street.

There is a lot of written evidence but it is not conclusive as to the true corner location, however no other conflicting evidence could be found therefore, the 2 ½" Aluminum Cap is the best evidence as to the location of the corner location. Additional information regarding the preparation of this certificate can be obtained by contacting: Bolton & Menk, Inc., 219 North Main Street, Fairmont, MN 56013.