| | Index No |
|--|---|
| CERTIFICATE OF LOCATION | OF GOVERNMENT CORNER |
| EAST QUARTER Corner of Section 14 , Township 102 N , Range 41 W , 5th P.M. | |
| STATE OF MINNESOTA, County of NOBLES | |
| At the corner location shown on the sketch: | |
| ☑ On 7/14/03 found a CAST IRON MONUMENT (BROKEN) | |
| □ Onplaced a | owered monument, \square removed monument (explain) |
| SKETCH OF REFERENCE TIES | |
| NORTHEAST CORNER | |
| NE 1/4 SEC 14-102-41 | NW 1/4 SEC 13-102-41 . |
| EAST 1/4 CORNER— SECTION 14-102-41 CAST IRON MONUMENT (BROKEN) | |
| SE 1/4 SEC 14-102-41 | SW 1/4 SEC 13-102-41 |
| SOUTHEAST CORNER | 80,800 N N N N SEU N N N N N N N N N N N N N N N N N N N |
| NAD83 (1996 ADJUSTMENT) STATE PLANE COORDINATES NOBLES COUNTY DATUM | |
| N= 150534.880 | |
| E= 562512.907 | BOOK: 110 PG. 42 I:\NOBLS\CERTIFICATES\2005\CAD\E14-102-41 |
| Statement of evidence relative to this corner location is on back of page. | |
| I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision. OFFICE OF THE COUNTY RECORDER County of | |
| Janele FOWLDS 4-24-86 DATE | I hereby certify that this document was filed in the Co. Recorders office atM. on the day of A.D., 19 |
| Registration No. <u>26748</u> | County Recorder |
| □ Professional Enginee | By, Deputy |

DOCUMENT NO. _____

☐ County Surveyor, ☐ County Engineer

Statement of Evidence

East Quarter Corner Section 14, Township 102 North, Range 41 West

Original Notes

Nobles County Highway Department records show a stake.

Nobles County Highway Department records show a stake, and also placed an iron pin.

Nobles County Highway Department records show an iron pin with the following ties:

Bottle Cap in Power Pole – Northeast 68.20' CL Tel Ped – Southwest 69.35' Stop Sign Post – Southeast 62.30' Stop Sign Post – Northwest 65.80'

On July 14, Bolton & Menk, Inc., Mankato, found a cast iron monument that appeared to be broken off.

The evidence is not conclusive as to the true corner location, however the occupational and collateral evidence suggest that this is a reasonable location as to the corner. Additional information regarding the preparation of this certificate can be obtained by contacting: Bolton & Menk, Inc., Mankato, MN.