Index	No	

CERTIFICATE OF LOCATION	OF GOVERNMENT CORNER			
EAST QUARTER Corner of Section 23 STATE OF MINNESOTA, County of NOBLES At the corner location shown on the sketch:	_, Township <u>102 N</u> , Range <u>41 W</u> , 5th P.M.			
□ On placed a	rered monument, removed monument (explain)			
SKETCH OF REFERENCE TIES				
NORTHEAST CORNER SECTION 23-102-41 3/4" IRON PIPE NET 1/4 SEC 23-102-41	NW 174 SEC 24-102-41			
EAST 1/4 CORNER— SECTION 23-102-41 5/8" REROD	AND THE RESIDENCE OF THE PROPERTY OF THE PROPE			
SE 1/4 SEC 23-102-41 -12592	SW 474 SEC 24-102-41			
NADB3 (1996 ADJUSTMENT) STATE PLANE COORDINATES NOBLES COUNTY DATUM N= 145224.442 E= 562522.461 SOUTHEAST CORNER SECTION 23-102-41 5/8" REROD	BOOK: 110 PG. 42 1:\NOBLS\CERTIFICATES\2005\CAD\E23-102-41			
Statement of evidence relative to this corner location is on back of page.				
I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.	County of			
JANELE FOWLDS DATE	I hereby certify that this document was filed in the Co. Recorders office atM. on the day of A.D., 19			
Registration No. <u>26748</u> ☑ Land surveyor, □ Professional Engineer	By, Deputy			
☐ County Surveyor, ☐ County Engineer	DOCUMENT NO			

Statement of Evidence

East Quarter Corner Section 23, Township 102 North, Range 41 West

Original Notes

1914	Nobles County Highway Department records show a stone monument being set.
1916	Nobles County Highway Department records show a stone monument.
1930	Nobles County Highway Department records show an iron pin.
1964	Nobles County Highway Department records show a reestablished iron pin.
1971	Nobles County Highway Department records show an iron pipe that was established as corner.
1991	Nobles County Highway Department records show a 5/8"x 12" rebar being placed.
1992	Nobles County Highway Department records show a 5/8"x4" rebar being placed in new bit, has the following ties: Nail & Disk in Power Pole – Southeast 84.9' "X" in CL Pipe – East 36.3'
	"X" on CL Pipe – West 38.6'
2003	On July 15, Bolton & Menk, Inc., Mankato, found a $5/8$ " rerod at the surface of a county road.