Index No
ERNMENT CORNER
2 N , Range <u>41 W</u> , 5th P.M.
E MONUMENT
., 🗆 removed monument (explain)
S
;
•
1/4 SEC 11-102-41
,
2642.33'
NORTHEAST CORNER———————————————————————————————————
1" SHAFT
1/4 SEC 14-102-41
,
BOOK: 110 PG. 42 I:\NOBLS\CERTIFICATES\2005\CAD\N14-102-41
on back of page.

CERTIFICATE OF LOCATION	OF GOVERNMENT CORNER
NORTH QUARTER Corner of Section 14  STATE OF MINNESOTA, County of NOBLES  At the corner location shown on the sketch:  On 7/14/03 found a 3/4" IRON PIF	, Township <u>102 N</u> , Range <u>41 W</u> , 5th P.M. PE OVER STONE MONUMENT
□ Onplaced a	wered monument, 🗆 removed monument (explain)
SKETCH OF REFERENCE TIES	
- N - SW 1/4 SEC 11-102-41	SE 1/4 SEC 11-102-41
2627.97'  NORTHWEST CORNER  SECTION 14-102-41  NAIL  N 1/4 CORNER  SECTION 14-102-41  3/4" IRON PIPE OVER STONE MONUMENT  AND MALE SEC 14-102-41	2642.33'  NORTHEAST CORNER  SECTION 14-102-41  1" SHAFT  NE 1/4 SEC 14-102-41
NAD83 (1996 ADJUSTMENT) STATE PLANE COORDINATES NOBLES COUNTY DATUM  N= 153193.779 E= 559876.303	BOOK: 110 PG. 42
Statement of evidence relative to this core	I:\NOBLS\CERTIFICATES\2005\CAD\N14-102-41
Statement of evidence relative to this corn  I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.	OFFICE OF THE COUNTY RECORDER
JANELE FOWLDS 4-24-06 DATE	I hereby certify that this document was filed in the Co. Recorders office atM. on the day of A.D., 19
Registration No. <u>26748</u> ☑ Land surveyor, □ Professional Engineer	County Recorder
☐ County Surveyor, ☐ County Engineer	By, Deputy DOCUMENT NO

## Statement of Evidence

North Quarter Corner Section 14, Township 102 North, Range 41 West

## Original Notes

Nobles County Highway Department records show a stone.

Nobles County Highway Department records show a stone, and placed an iron pin with the following ties:

Gate Post – Northeast 35.25' Cor Post – Southwest 32.40' FE Post – Southeast 60.29'

On July 14, Bolton & Menk, Inc., Mankato, found a 3/4" iron pipe over a stone.

The evidence is not conclusive as to the true corner location, however the occupational and collateral evidence suggest that this is a reasonable location as to the corner. Additional information regarding the preparation of this certificate can be obtained by contacting: Bolton & Menk, Inc.; Mankato, MN.