	N OF GOVERNMENT CORNER	
NORTHEAST Corner of Section STATE OF MINNESOTA, County ofNOBLI	13 Township 102N, Range 43W, 5 P.M.	
At the corner location shown on the sketch:		
☑ On Aug. 3.1988 found a 3/4 inch ir	on pin flush	
□ left monument as found, □ low	ered monument, 凶 removed monument (explain)	
	Department of Transportation cast iron	
☐ TI02N R43W	REFERENCE TIES SECTION 7 TI02N R42W	
Monument is on centerline Trunk Highway 91, with no east-west occupation lines	vel Shoulder	
Gravel	Chisled "x" in concrete light base	
Chisled "x" in concrete slab SECTION 13 TIO2N R43W RAMP	SECTION 18	
Statement of evidence relative to this corner location is on back of page.		
I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision. **Description** **Automatical School*** **Description** **Registration No	OFFICE OF THE COUNTY RECORDER County of Dobles I hereby certify that this document was filed in the Co. Recorders affice at 4.35 P. M. on the 15th day of County Recorder A.D., 19 91 County Recorder Arrent Howard,	
☐ Land Surveyor, ☐ Professional Engineer	ByDeputy	
☐ County Surveyor, ☐ County Engineer	DOCUMENT NO. 245763	

Statement of Evidence: Northeast Corner of Section 13 T102N R43W 5th P.M.	
1891 and 1911	Nobles County Highway Department records show a stone at the corner.
July-Aug., 1918	W. A. Saxon, Nobles County Surveyor, at the request of the County Board, surveyed part of State road Number 5 and notes there was an old stone at Campbells corner.
1959	Nobles County Highway records show an iron pin.
March 21, 1974	S. Baker, Minnesota Highway Department Survey Crew Chief, found a 3/4 inch iron stake flush with the bituminous surface 18 inches east of the Trunk Highway 91 centerline stripe. This is 84 feet north of a P.O.T. at the I-90 ramp terminus.
Sept. 17, 1975	D. Almquist, Minnesota Department of Transportation Survey Crew Chief, found a 3/4 inch iron stake flush with the road surface and 1 foot east of the Trunk Highway 91 centerline stripe.
Feb. 13, 1978	Minnesota Department of Transportation Survey crew members Foster, Verdoorn, and Warner found a 3/4 inch iron pin as described above
Aug. 3, 1988	O. Berkness, Senior Highway Technician for the Minnesota Department of Transportation, found the 3/4 inch iron pin flush with the bituminous surface, and placed a Minnesota Department of Transportation cast iron monument flush with bituminous surface.
	The inplace location of the iron pin is compatible with the occupation lines within the section. An analysis of the Statement of Evidence and the field measurements indicates the iron pin is in a reasonable location.
	For additional information, including field measurements and photographs, contact the Minnesota Department of Transportation in Windom, Minnesota.