Index	No.	_

CERTIFICATE OF LOCATION	OF GOVERNMENT CORNER	
NORTHEAST Corner of Section 13 STATE OF MINNESOTA, County of NOBLES At the corner location shown on the sketch: On 11/08/02 found a GEAR SPIKE	, Township <u>102 N</u> , Ronge <u>44 W</u> , 5th P.M.	
✓ left monument as found, ☐ lowers C: Onplaced a	ered monument, 🗆 removed monument (explain)	
SKETCH OF REFERENCE TIES		
- N - NE CORNER SECTION 12-102-44 5/8" REROD	7	
SECTION 12-102-44 \$20.24	SECTION 7-102-43 N 1/4 CORNER SECTION 18-102-43 3/4" IRON PIPE	
SECTION 13-102-44 2989	2662.20' NE CORNER SECTION 13-102-44 GEAR SPIKE SECTION 18-102-43	
NAD83 (1996 ADJUSTMENT) STATE PLANE COORDINATES NOBLES COUNTY DATUM N= 152967.830 E= 472634.775	EAST 1/4 CORNER SECTION 13-102-44 CAST IRON MONUMENT BOOK: NOBLES CO. PG. 3	
!:\NOBLS\CERTIFICATES\NE13-102-44		
Statement of evidence relative to this corner location is on back of page.		
I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision. OFFICE OF THE COUNTY RECORDER County of		
JANELE FOWLDS DATE	I hereby certify that this document was filed in the Co. Recorders office atM. on the day of A.D., 19	
Registration No. <u>26748</u>	County Recorder	
☑ Land surveyor, ☐ Professional Engineer	*	
☐ County Surveyor, ☐ County Engineer	DOCUMENT NO	

Statement of Evidence

Northeast Corner Section 13, Township 102 North, Range 44 West

According to the Original Survey notes located in the Secretary of States Office, the Northeast Corner of Section 13 was established as follows: North on the true line between Ranges 43 & 44, Township 102, between Sections 13 & 18, Variance 12 degrees, at 80.00 chains set a post in mound for the corner to Sections 7, 18, 12, & 13.

Nobles County Highway Department records show an iron pin.

1930's State of Minnesota Department of Highways, Right of Way Map, Nobles County, S.P. 5301 and S.P 5302 shows the corner being 11.8' North of the centerline of T.H. 16.

Nobles County Highway Department records show an iron pin.

Nobles County Highway Department records show that an iron pin was placed, with ties as follows:

Telephone Pole – Northwest 70.48' Telephone Pole – Northeast 85.15' "X" in wing wall – Southwest 62.12' "X" in wing wall – Southeast 61.81' 11.85' North of T.H. 16

On November 8, Bolton & Menk, Inc. found a Gear Spike flush with bituminous, 12' North of the centerline highway.

The evidence is not conclusive as to the true corner location, however the occupational and collateral evidence suggest that this is a reasonable location as to the corner. Additional information regarding the preparation of this certificate can be obtained by contacting: Bolton & Menk, Inc., Mankato, MN.