| CERTIFICATE OF LOCATION OF GOVERNMENT CORNER | |
|--|---|
| Northeast Corner of Section 22 , Township 103N , Range 39W , 5th P.M. | |
| STATE OF MINNESOTA, County of <u>Nobles</u> At the corner location shown on the sketch On <u>9/16/05</u> found a <u>60D spike at center of road intersection.</u> | |
| left monument as found lowered monument, iremoved monument (explain) On 10/03/05 placed a 1" iron pipe with red survey cap #43803. | |
| SKETCH OF REFERENCE TIES | |
| TOP OF UTILITY— WARNING POST | -5/8" IRON STAKE |
| 190TH 49.50 | |
| OF LICENSES LA 43803 STATES | NW CORNER OF TRANSFORMER |
| SURVEYOR HORESON | NAD 83 (1996) US STATE PLANE 1983 MN SOUTH 590651.20N 2229927.21E |
| Statement of evidence relative to this corner location is on page 2. | |
| ! hereby certify that this document and the data contained herein was prepared by me or under my direct supervision. Manual Ray Cylin 11/04/05 SIGNATURE DATE | OFFICE OF THE COUNTY RECORDER I hereby certify that this document was filed in the Co. Recorder's Office at on the |
| MN. LICENSE NO. 43803 X Land Surveyor, Professional Engineer County Surveyor, County Engineer | County Recorder, Deputy DOCUMENT NO |
| | |

Statement of Evidence

1867 Original Township Subdivision was surveyed by T.B. Walker.

Nobles Co. Hwy. Dept. had no history of this corner.

2005 Gerald Vickerman PLS and Jeremy Lund, with Zieske Land Surveying, found 60D spike, removed spike and excavated below with backhoe and found nothing. Placed 1" iron pipe with red survey cap #43803 at same position was 60D spike at center of road intersection.



COMPARED

DOCUMENT NUMBER A 306830

Certified, Filed and or Recorded on NOV. 07,2005 AT 05:10:10PM

NOBLES COUNTY RECORDER LYNN M. WILSON

507-372-8216