514 300 104 21

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER	
NORTH QUARTER Corner of S	Section 14 , Township 104N , Range 41W
5th Principal Meridian, State of Minnesota, Cour	
At the corner location shown on the sketch:	
On found	
☐ left monument as found ☐ los	wered monument  removed monument (explain)
X On11/09/2017 placed a <u>5/8" REBAR</u> DATE RUNNING SOUTH.	CAPPED 49563 ON CENTERLINE AND ON LINE WITH A FENCE
SKETCH OF	REFERENCE TIES
	SET 3/8" REBAR WITH REFERENCE CAP
נט	
	36.05
\$80°W	120TH STREET
	<u>\$74</u> °E
rO	-C
SET PK IN PP	SET PK IN PP —
	4
	N.T.S.
Statement of evidence for this o	corner location is on back of this page.
I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed La Surveyor under the laws of the State of Minnesota.	On CUMENT NUMBER A 357565  Certified, Filed and or Recorded of March 07, 2018 2:45 PM
Signature + Mal-	NOBLES COUNTY RECORDER
Signature 75 W.C.  Date 1/24/18 License No. 49563	LYNN M. WILSON 507-295-5268
Title:	Pagas: 2
X Land Surveyor Professional Engineer	
☐ County Surveyor ☐ County Engineer	

## KRIS WROOLIE Minnesota License No. 49563

## **Statement of Evidence:**

J-19

North Quarter Corner of Section 14, Township 104 North, Range 41 West, 5<sup>th</sup> Principal Meridian, Nobles County, Minnesota.

1868-Deputy Surveyor set a post in mound with pits.

1903 - The County Surveyor in Book 22, Page 135 gives distance along the north line of section 14. The distance to the NE14 is 2651.4 and 2656.5 to the NW14.

2017-On November 28th, Westwood Professional Services field crews searched the area and found nothing. The distance given in 1903 across the north line of section 14 is 5307.90' and Westwood measures 5296.73'. Set #5 rebar with LS 49563 cap at centerline and fence line south. This location fits 3.5' from proportioned distance using 1903 survey and is deemed the best available evidence of the corner location. Ties were found or set as shown on the front of this certificate.

Analysis of the recovered data, field evidence and survey measurements, indicates that the monument found is the correct perpetuation of this corner. For additional information concerning this corner please contact Westwood Professional Services.

129/18