51/4 Sec 29 104 11

	. 5			- 4	1	19	P	14
		. 9	A Arms	ا المحصيفا	12	1000	10 20 20	i /
nde	X		V	-7	1 or All		All	iž

CERTIFICATE OF LOCATION	OF GOVERNMENT CORNER						
NORTH QUARTER Corner of Section	on <u>32</u> , Township <u>104N</u> , Range <u>41W</u>						
5th Principal Meridian, State of Minnesota, County o	The second secon						
At the corner location shown on the sketch:							
X On <u>11/09/2017</u> found <u>NOTHING.</u>							
☐ left monument as found ☐ lowered	= removed monument (explain)						
X On <u>11/09/2017</u> placed a <u>5/8" REBAR CAPE</u> WITH FENCE LINES RUNNING NORTH AND SOUTH.							
SKETCH OF REF	TEDENOE TIES						
SKETCH OF KEP	ERENCE HES						
	SET PK IN PP						
150TH STREET							
SET 3/8" REBAR WITH REFERENCE CAP	CENTER OF LONE 4" POST						
	N.T.S.						
Statement of evidence for this corner							
I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.	Certified. Filed and or Recorded o March 08, 2018 9:40 AM						
Signature — + SNL	NOBLES COUNTY RECORDER						
Signature 75 No. 29563 Date 1/29/18 License No. 49563	LYNN M. WILSON 507-295-5268						
Title:	Pages: 2						
X Land Surveyor Professional Engineer							
County Surveyor County Engineer							

KRIS WROOLIE Minnesota License No. 49563

Statement of Evidence:

V-7

North Quarter Corner of Section 32, Township 104 North, Range 41 West, 5th Principal Meridian, Nobles County, Minnesota.

1868-Deputy Surveyor Richard N. L. Jeorlt, set a post in mound with pits for the section corner.

1900-Surveyor's Record Book A-2, page 382, prepared by County Surveyor M.S. Smith shows a stone at the corner location. Distance to the SW corner of Sec. 28 T.104 R.41 is shown to be 2650.1 ft.

2017-On November 9th, Westwood Professional Services found nothing. Set a 5/8" rebar capped 49563 on E/W centerline and on line with fence lines running north and south. E/W centerline and fence line extension intersection fits the 1900 survey distances. Set 3 ties.

Analysis of the recovered data, field evidence and survey measurements, indicates that the monument found is the correct perpetuation of this corner. For additional information concerning this corner please contact Westwood Professional Services.

1/29/18