Index	P-5

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER	
EAST QUARTER Corner of Section	n <u>19</u> , Township <u>104N</u> , Range <u>41W</u>
5th Principal Meridian, State of Minnesota, County o	li l
At the corner location shown on the sketch:	2
X On 11/10/2017 found a 1/2" OPEN IRON PIPE +/- 3 FT WEST OF NORTH/SOUTH  CENTERLINE AND ON LINE WITH FENCE RUNNING WEST.	
🛛 left monument as found 🔲 lowered	monument  removed monument (explain)
On placed a	
SKETCH OF REFERENCE TIES	
SET 3/8" REBAR  PURPLE AND THE	SET 3/8" REBAR  SET 3/8" REBAR  N.T.S.
Statement of evidence for this corne	the commence of the commence o
I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.	DOCUMENT NUMBER A 35757: Certified, Filed and or Recorded o March 07, 2018 3: 35 PM
Signature # Signature	Lynn Willson
Date 1/29/18 License No. 49563	NOBLES COUNTY RECORDER LYNN M. WILSON 507-295-5268
Title:	Pages: 2
X Land Surveyor Professional Engineer	
☐ County Surveyor ☐ County Engineer	

## KRIS WROOLIE Minnesota License No. 49563

## **Statement of Evidence:**

P-5

East Quarter Corner of Section 19, Township 104 North, Range 41 West, 5<sup>th</sup> Principal Meridian, Nobles County, Minnesota.

1868-Deputy Surveyor Richard N. L. Jeorlt, set a post in mound with pits for the section corner.

1895-On September 16th, in Surveyor's Record Book A-2, page 202, prepared by County Surveyor M.S. Smith, shows he found the original stake with the mound at the corner positron. Set an iron rod, 1-3/8" x 2.2'.

2011-A survey dated 09/13/2011 prepared by Perry L. Zieske, for project number N 1016 S, shows a 1/2" iron pipe in place for the corner position.

2017-On November 10th, Westwood Professional Services found a 1/2" iron pipe +/-3 ft. west of N/S centerline and online with fence running west. Monument fits distances on the 2011 Zieske Survey. Accepting the found 1/2" iron pipe as the position of the corner.

Analysis of the recovered data, field evidence and survey measurements, indicates that the monument found is the correct perpetuation of this corner. For additional information concerning this corner please contact Westwood Professional Services.

81,05,1