| Index _ | P-9 | V-2000 |
|---------|-----|--------|

| CERTIFICATE OF LOCATION OF GOVERNMENT CORNER | | | |
|---|---|--|--|
| EAST QUARTER Corner of Section | | | |
| 5th Principal Meridian, State of Minnesota, County of Nobles. | | | |
| At the corner location shown on the sketch: | | | |
| X On <u>11/10/2017</u> found a <u>1/2" OPEN IRON PIPE</u> A FIELD LINE EAST. | E 7.5 FT WEST OF NORTH/SOUTH ROAD MATCHING | | |
| $\overline{\mathbb{X}}$ left monument as found $\overline{\ }$ lowered n | nonument removed monument (explain) | | |
| Onplaced a | 200 42 MO | | |
| | | | |
| SKETCH OF REFERENCE TIES | | | |
| SET PK IN S. END OF CMP | 3°E 8° O SET 3/8" REBAR N- | | |
| Statement of evidence for this corner location is on back of this page. | | | |
| I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota. | DOCUMENT NUMBER A 357580 Certified, Filed and or Recorded on March 07, 2018 3:45 PM | | |
| Signature # W.L. | Lynn Wilson | | |
| Date 1/29/18 License No. 49563 | NOBLES COUNTY RECORDER LYNN M. WILSON 507-295-5268 | | |
| Title: | Pagas: 2 | | |
| X Land Surveyor Professional Engineer | | | |
| ☐ County Surveyor ☐ County Engineer | | | |

KRIS WROOLIE Minnesota License No. 49563

Statement of Evidence:

P-9

East Quarter Corner of Section 20, Township 104 North, Range 41 West, 5th Principal Meridian, Nobles County, Minnesota.

1868-Deputy Surveyor set a post in mound with pits.

1895 - Nobles County Highway Department "Corner Ties Book" notes an iron pin marking the corner location.

2011 - Nobles County Highway Department "Corner Ties Book" notes an iron pin marking the corner location.

2011 - Perry Zieske, LS 23008, survey shows a 1/2" iron pipe marking the corner location.

2017 - Westwood field crews recover a 1/2" iron pipe 7.5' east of centerline of north/south road and matching a field line east. The location matches the location given in the 2011 Zieske survey. Ties were found or set as shown on the front of this certificate.

Analysis of the recovered data, field evidence and survey measurements, indicates that the monument found is the correct perpetuation of this corner. For additional information concerning this corner please contact Westwood Professional Services.

: 101/6/2.