12



Index ____G-9

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER	
EAST QUARTER Corner of Section	on <u>8</u> , Township <u>104N</u> , Range <u>42W</u>
5th Principal Meridian, State of Minnesota, County of Nobles.	
At the corner location shown on the sketch:	
X On <u>12/06/2017</u> found a <i>NOTHING</i> . DATE	
	d monument
X On <u>12/27/2017</u> placed a <u>1/2" REBAR CAPF</u> DATE NOTES FROM 1900 RESURVEY.	PED 49563 0.4' DOWN AT PROPORTIONED DISTANCE USING
SKETCH OF REFERENCE TIES	
SET MAG IN SW. CORNER IN FIBER OPTIC SIGN	
SET MAG IN SW. 00/Z FACE FENCE 8 00/0 CORNER POST	
DRIVEWAY S87 MAG IN S. END OF 18" CMP	
N.T.S. Statement of evidence for this corner location is on back of this page.	
I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.	Pago.
Signature <u>+5 W.l.</u> Date <u>2/7/18</u> License No. 49563	DOCUMENT MILITERS A 357479 Certified, Filed and or Recorded on March 06, 2018 10, 55 AM
	Lynn Willson
Title:	NOBLES COUNTY RECORDER
X Land Surveyor ☐ Professional Engineer	LYNN M. WILSON 507-295-5266
☐ County Surveyor ☐ County Engineer	Pages: 2

KRIS WROOLIE Minnesota License No. 49563

Statement of Evidence:

G-9

East Quarter Corner of Section 8, Township 104 North, Range 42 West, 5th Principal Meridian, Nobles County, Minnesota.

1868-Deputy Surveyor set a post in mound with pits.

1900- Nobles County Highway Department "Corner Ties Book" calls for a stone to mark the corner location.

1938 - Nobles County Highway Department "Corner Ties Book" calls for a stone to mark the corner location

2017- Westwood Professional Services located centerline of a north-south road. No additional evidence was recovered for the corner. A 5/8" rebar capped LS 49563 was place online between section corners and proportioned using distances from the 1900 survey. This position agrees closely with centerline and occupation lines to the east and west. Ties were set as shown on the front of this certificate.

Analysis of the recovered data, field evidence and survey measurements, indicates that the monument found is the correct perpetuation of this corner. For additional information concerning this corner please contact Westwood Professional Services.

ナラハル