Index	No.		

CERTIFICATE OF LOCATION (OF GOVERNMENT CORNER		
SOUTHEAST Corner of Section 11. Tov	vnship <u>104</u> , Range <u>42</u> , <u>5TH</u> P.M.		
STATE OF MINNESOTA, County ofAt the corner location shown on the ske			
☐ left monument as found, ☐ lowe	ered monument, 🔲 removed monument (explain)		
Onset			
Sketch of re	eference ties		
MINIMUM MAINTENANCE SIGN 1.5" IRON PIPE 120th ST DIRT ROAD STOP SIGN N: 632,135.85 E: 2,141,037.10 MN SOUTH, NAD 83 NOT TO SCALE	STREET SIGN FELLOWS AVE 120th ST ELECTRICAL TRANSFORMER		
Statement of evidence relative to this corner location is a	on back page		
I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.	OFFICE OF THE COUNTY RECORDER County of		
Thomas V 2011 Date Registration No. 44565 X Land Surveyor, Professional Engineer County Surveyor, County Engineer	I hereby certify that this document was filed in the Co. Recorders office atM. on the day of A.D. , 20 County Recorder		

STATEMENT OF EVIDENCE:

SOUTHEAST CORNER, SECTION 11, T. 104 N., R. 42 W., NOBLES COUNTY, MINNESOTA

1868 Jewett & Howe, US. Deputy Surveyors, monumented corner.

1/06/2006 Ulteig Engineers, Inc., Survey Crew, Brian Payne Party Chief, found a 1.5" iron pipe at the C/L intersection of the roads.

Ties: NE-48.7' to nailed "X" on wood, corner, fence post;

SE-28.8' to "street sign" post;

SW-33.3' to "stop sign" post.