Index No.	
-----------	--

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER		
SOUTHWEST Corner of Section 26, Township 104, Range 42, 5TH P.M.		
STATE OF MINNESOTA, County of NOBLES  At the corner location shown on the sketch :  \text{\text{\$\sum}} On 1/09/2006 found _A 1" IRON PIPE AT THE C/L INTERSECTION		
OF THE TWO ROADS.    State   S		
☐ On set		
Sketch of reference ties		
CO. HWY. 69 150th ST  ASPHALT  N: 616,405.69 E: 2,135,498.33 MN SOUTH, NAD 83 NOT TO SCALE	GRAVEL GRAVEL GRAVEL GRAVEL GRAVEL GRAVEL AND SALE SIGN AND STATE OF STATE	
Statement of evidence relative to this corner location is on back page		
I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.	OFFICE OF THE COUNTY RECORDER  County of	
Thomas Edit Date  Registration No44563  X Land Surveyor, Professional Engineer	1 hereby certify that this document was filed in the Co. Recorders office atM. on the day of A.D. , 20  County Recorder Deputy  DOCUMENT NO	
☐ County Surveyor, ☐ County Engineer	DOGUNENT NO.	

ε

## STATEMENT OF EVIDENCE:

SOUTHWEST CORNER, SECTION 26, T. 104 N., R. 42 W., NOBLES COUNTY, MINNESOTA

1868 Jewett & Howe, US. Deputy Surveyors, monumented corner.

1900 Nobles Co., found stone on corner, no ties.

Madsen Land Surveying, found a 1" iron pin, 4" deep. 2/15/2000

Ties: NW-60.7' to SE corner, electrical box;
SW-67.5' to C/L of E post of "minimum maintenance sign";
NE-73.2' to C/L of W post of "minimum maintenance sign".

Ulteig Engineers, Inc., Survey Crew, Brian Payne Party Chief, found 1/09/2006 a 1" iron pipe at the C/L intersection of 150th Street & Erickson Ave.

Ties: NW-60.6' to SE corner of electrical transformer box; SW-67.6' to "minimum maintenance sign" post; SE-39.4' to "street sign" post.